	RCC OIL/GAS REGUI	ATORY OFFICE	er er vä		ALTZ.
DATE:	21/94		3 , 1, 3		X] New Situation sponse to Request
					[] Follow-Up
		LOCATION	SW SE SE	<u>sec</u>	<u>T</u>
OPERATOR:	Pickrell Drilling Co	ompany, Inc.	LIC	ENSE #: _	5123
ADDRESS: _	110 N. Market, Ste.	205			
ADDRESS:	Wichita, KS 67202		<u>Lea</u>	SE/WELL NU	MBER: Sargent "C" #
PHONE #:	316-262-8427		COT	Nes	
				AP1#1	.5–135–23,813
LEAS	SE INSPECTION:	COMPL?	AINT:	FIELD	REPORT: X
DELGOV FOR	TANKE CHI CARTON.	Alternate II	cementing		
REASON FOR	R INVESTIGATION:			-	
PROBLEM:			· · · · · · · · · · · · · · · · · · ·		
					
PERSONS CO	NTACTED:				
FINDINGS:	I arrived on locat	ion at 10 a.m.	The port	collar was o	pened at 1812'. Allie
pumped in 35	50 sx 60/40 Pozmix 8%	gel with ½# fl	oseal. Cir	culated 4 baı	rels to the pit.
The job was	started at 10:15 a.m.	and complete	at 10:47.a.	m.	
				· · · · · · · · · · · · · · · · · · ·	
	*	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
·					
	·			, , , , , , , , , , , , , , , , , , , ,	
			<u>PH</u>	OTOS TAKEN	•
ACTION/REC	COMMENDATIONS: Jo	ob completed.			
· · · · · · · · · · · · · · · · · · ·	<u> </u>				<u>'</u>
		· · · · · · · · · · · · · · · · · · ·			
	•		- 	· · · · · · · · · · · · · · · · · · ·	
			12	<u></u>	B
			Trong	<u> </u>	
			A", 8	BY	Steve Middleton
			U\		4/21/94

Retain 1 copy District Office Send 1 copy Conservation Division