

ALT2

KCC OIL/GAS REGULATORY OFFICE

DATE 4/10/95

- New Situation
- Response to Request
- Follow-up

OPERATOR Palomino Petroleum, Inc. # 30742

NAME 4924 SE 84th St.

& ADDRESS Newton, KS 67114-8827

PHONE NO. _____

OPER. _____ OTHER _____

App. LOCATION C SE SE, SEC 8, T 17 S, R 24 W

LEASE Tilley Well # 5

COUNTY Ness

API#15-135-23,869 0000

REASON FOR INVESTIGATION: Alternate II completion

PROBLEM:

PERSON(S) CONTACTED:

FINDINGS: Opened port collar at 1764' and Halliburton pumped in 265 sx cement (Halliburton lite). Circulated cement to pit. Started at 12:30 p.m. and completed at 1 p.m.

ACTION/RECOMMENDATIONS: Alternate II cementing completed.

photos taken: _____

Retain 1 copy Joint District Office
Send 1 copy Conservation Division

By Steve Middleton
4/10/95

LEASE INSPECTION

COMPLAINT

FIELD REPORT

RECEIVED
STATE CORPORATION COMMISSION
APR 14 1995
CONSERVATION DIVISION
WICHITA, KANSAS