

KCC OIL/GAS REGULATORY OFFICE

API # 15-135-24105-0000

ATT. Virginia

Date 4-20-2000

- New Situation
- Response to Request
- Follow-up

ALT 2

Operator Carmon Schmidt #

Address

Location NW, Sec 4, T 18S, R 24W

Lease Jones Estate Well # 2

Phone No. Oper. Other

County Ness

Reason for Investigation: Alt II

Problem:

Person(s) Contacted:

Findings: 8 5/8" @ 213'

7.D. @ 4504

5 1/2" @ 4480'

DV Tool @ 1648'

Cemented with 400 SXS 60/40 670 gel 1/4" P10 Seal

Cement Circulate - about 100 SXS to pit

photos taken:

Action/Recommendations: None. Cement Circulated

- Lease Inspection
- Complaint
- Field Report

By Michael J. Macer

Retain 1 copy Joint District Office
Send one copy Conservation Division

RECEIVED
STATE CORPORATION COMMISSION

APR 25 2000

CONSERVATION DIVISION
Wichita, Kansas

LEASE INSPECTION

- YES NONE COMMENTS
- I.D. Sign
- Tank Battery ; Condition: good questionable overflowing
- Pits, tank battery ; Fluid depth _____ ft.; approx. size _____ ft x _____ ft
- Pit, injection site ; Fluid depth _____ ft.; approx. size _____ ft x _____ ft
- Gas venting
- Oil spill evidence
- Saltwater evidence ; Surface flow _____; seepage _____
- Saltwater pipelines ; Seepage visible Yes/No; tested for leaks Yes/No
- Flowing holes
- Abandoned wells
- TA wells ; Potential poll. Prob. _____; currently producing _____
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- Monitoring records
- Gauge connections ; tubing _____; T/C annulus _____; C/SP annulus _____
- Gauge connections ; tubing _____; T/C annulus _____; C/SP annulus _____
- Gauge connections ; tubing _____; T/C annulus _____; C/SP annulus _____
- Gauge connections ; tubing _____; T/C annulus _____; C/SP annulus _____

Lease cleanliness: Very good _____ satisfactory _____ poor _____ very bad _____

Water samples taken _____

Reports prepared _____

+	+	+	+
+	+	+	+
+	+	+	+
+	+	+	+