

KCC OIL/GAS REGULATORY OFFICES

Date: 08/03/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5144  
 Op Name: Mull Drilling Company, Inc.  
 Address 1: 1700 N Waterfront Pkwy  
 Address 2: Bldg. 1200  
 City: Wichita  
 State: Kansas Zip Code: 67206 -6637  
 Operator Phone #: (316) 264-6365

API Well Number: 15-135-25,421-00-00  
 Spot: NW-NE-NE-SE Sec 11 Twp 17 S Rng 24  E /  W  
 2561 (2568) Feet from  N /  S Line of Section  
 647 (643) Feet from  E /  W Line of Section  
 GPS: Lat: 38.58789 Long: 99.93925 Date: 8/3/12  
 Lease Name: Smith-Rufenach Unit Well #: 1-11  
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 233' W/165sxs cement  
 TD @ 4550'  
 5-1/2" @ 4537' W/150sxs cement  
 Port Collar @ 1798' cement with 150sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

RECEIVED  
 AUG 13 2012  
 KCC WICHITA

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met.

Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

*Michael Maier*

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

AUG - 9 2012

Form: 02/22/2008

KCC DODGE CITY

*PMW*

Date: 08/03/12

District: 01

License #: 5144

Op Name: 5144

Spot: NW-NE-NE-SE Sec 11 Twp 17 S Rng 24  E  W

County: Ness

Lease Name: Smith-Rufenach Unit Well #: 1-11

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.421-00-00	2568FSL 643FEL	NW-NE-NE-SE	38.58789-99.93925	1-11	New well, Alt. II completed