KCC OIL/GAS REGULATORY OFFICES

| Date: <u>06/15/12</u> | District: <u>01</u> | Case #: |
|--|--------------------------------|--|
| | New Situation | Lease Inspection |
| | Response to Request | Complaint |
| | Follow-Up | Field Report |
| | 45.000 | |
| Operator License No: 32331 | | =21779-00-00 |
| Op Name: DK Operating Inc | | Sec 17 Twp 21 S Rng 22 E / W |
| Address 1: 24583 NW 208 Road | | Feet from N/ S Line of Section |
| Address 2: | • • | Feet from Feet from VE/W Line of Section |
| City: Jetmore | | Long: 99.75526 Date: 6/15/12 |
| State: <u>Kansas</u> Zip Code: <u>67854 -5311</u> | | Well #: <u>1-17</u> |
| Operator Phone #: <u>(620) 357-6152</u> | County: Hodgeman | |
| Reason for Investigation: | | |
| Company requested state witness for alterna | te II cementing | |
| Problem: | | |
| None | | |
| | | |
| Persons Contacted: | | |
| None | | |
| Findings: | | |
| 11:00am 8 5/8" surface casing @ 258' w/ 150sx cemel 5 1/2" production casing @ 4359' w/ 125sx ce Port collar opened @ 1458' Swift Services pu collar closed. | ement | ent, with 20sx circulating to pit. Port |
| Action/Recommendations: Follow | v Up Required Yes ✓ No | Date: |
| Alternate II cementing requirements have be | <u></u> | |
| Trace in comonting requirements have be | on mot. | |
| Verification Sources: | | Photos Taken: 0 |
| T-I Database District Files Other: On-site with SECEIVED Retain I Conv. District Office | TA Program Courthouse By: Kenr | ny Sullivan // RECEIVED |
| Send I Copy to Conservation Divisiti N 1 5 2012 | | JUN 2 1 2012 com: |
| KCC DODGE CITY | | KCC MICHITA |

KCC WICHITA