

KCC OIL/GAS REGULATORY OFFICES

Date: 06/07/12

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-25,391-00-00

Op Name: American Warrior

Spot: SE-NW-SW-NE Sec 13 Twp 19 S Rng 22 E / W

Address 1: P.O. Box 399

1950 (1965) Feet from N / S Line of Section

Address 2: _____

2100 (2092) Feet from E / W Line of Section

City: Garden City

GPS: Lat: 38.40195 Long: 99.70346 Date: 6/7/12

State: Kansas Zip Code: 67846 -0399

Lease Name: Schwien Well #: 3-13

Operator Phone #: _____

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 223W/150sxs cement
TD @ 4352'
5-1/2" @ 4351'W/175sxs cement
Port Collar @ 1432' cemented with 100sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt.II requirements have been met

RECEIVED
JUN 28 2012
KCC WICHITA

Verification Sources:

Photos Taken: _____

| | | |
|---------------------------------------|--|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| Other: _____ | | |

RECEIVED

By: Michael Maier
Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

JUN 26 2012

KCC DODGE CITY

Form: 02/22/2008

RAY

Date: 06/07/12

District: 01

License #: 4058

Op Name: 4058

Spot: SE-NW-SW-NE Sec 13 Twp 19 S Rng 22 E W

County: Ness

Lease Name: Schwieh Well #: 3-13

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

| API Number | Footages | Spot Location | GPS | Well # | Well Status |
|---------------------|--------------------|---------------|-------------------|--------|-----------------------------|
| 15-135-25.391-00-00 | 1965FNL 2092FEL | SE-NW-SW-NE | 38.40195-99.70436 | 3-13 | New well, Alt. II completed |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |