

KCC OIL/GAS REGULATORY OFFICES

Date: 06/28/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-25.408-00-00

Op Name: American Warrior

Spot: SW-NE-NW-NW Sec 36 Twp 19 S Rng 22  E /  W

Address 1: P.O. Box 399

425 (427) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

957 (987) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.36264 Long: 99.71082 Date: 6/28/12

State: Kansas Zip Code: 67846 -0399

Lease Name: Williams Well #: 10

Operator Phone #: \_\_\_\_\_

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 224W/150sxs cement  
TD @ 4392'  
5-1/2" @ 4391'W/145sxs cement  
Port Collar @ 1462' cemented with 150sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

RECEIVED  
JUL 12 2012  
KCC WICHITA

Verification Sources:

Photos Taken: 0

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
Other: _____		

By: Michael Maier  
*Michael Maier*

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

KCC DODGE CITY

Form: 02/22/2008

*11912*

Date: 06/28/12

District: 01

License #: 4058

Op Name: 4058

Spot: SW-NE-NW-NW Sec 36 Twp 19 S Rng 22  E  W

County: Ness

Lease Name: Williams Well #: 10

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.408-00-00	427FNL 987FWL	SW-NE-NW-NW	38.36264-99.71082	10	New well, Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division