

KCC OIL/GAS REGULATORY OFFICE

15-101-21379-0001

Date 6-9-99

- New Situation
- Response to Request
- Follow-up

Operator Wabash Energy # 31251

Address P.O. Box 595 Lawrenceville, IL Location SW, Sec 10, T 16 S, R 30 W
62439

Lease UPRK Well # 00001

Phone No. Oper. 68-943-3365 Other _____ County Lane

Reason for Investigation: Alt II

Problem: _____

Person(s) Contacted: _____

Findings: Surf - 238'

TD - 4464

5 1/2 @ 4462 w/ 150 SXS

Port collar - 2126' Cement with 2255XS SMDL 2% CC & F10 seal

Cement did Circulate

photos taken: _____

Action/Recommendations: None Cement Circulated

RECEIVED
 KANSAS CORP. CLERK
 1999 JUN 17 12:38
 6-17-99

- Lease Inspection
- Complaint
- Field Report

By Michael Mann

Retain 1 copy Joint District Office
Send one copy Conservation Division

LEASE INSPECTION

- YES NONE COMMENTS
- I.D. Sign
- Tank Battery ; Condition: good questionable overflowing
- Pits, tank battery ; Fluid depth ____ ft.; approx. size ____ ft x ____ ft
- Pit, injection site ; Fluid depth ____ ft.; approx. size ____ ft x ____ ft
- Gas venting
- Oil spill evidence
- Saltwater evidence ; Surface flow _____; seepage _____
- Saltwater pipelines ; Seepage visible Yes/No; tested for leaks Yes/No
- Flowing holes
- Abandoned wells
- TA wells ; Potential poll. Prob. _____; currently producing _____
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- SWD/ER Injection well ; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- Monitoring records
- Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____
- Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____
- Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____
- Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____

Lease cleanliness: Very good: _____ satisfactory _____ poor _____ very bad _____

Water samples taken _____

Reports prepared _____

+	+	+	+
+	+	+	+
+	+	+	+
+	+	+	+