

KCC OIL/GAS REGULATORY OFFICES

Date: 08/27/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
 Op Name: American Warrior  
 Address 1: P.O. Box 399  
 Address 2: \_\_\_\_\_  
 City: Garden City  
 State: Kansas Zip Code: 67846 -0399  
 Operator Phone #: \_\_\_\_\_

API Well Number: 15-083-21,822-00-00  
 Spot: SW-NW-NE-NW Sec 36 Twp 22 S Rng 23  E /  W  
 363 (332) Feet from  N /  S Line of Section  
 1648 (1646) Feet from  E /  W Line of Section  
 GPS: Lat: 38.10094 Long: 99.80162 Date: 8/27/12  
 Lease Name: Hodegeman-O'brate Well #: 4-36  
 County: Hodgeman

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 225W/150sxs cement  
 TD @ 4485'  
 5-1/2" @ 4480'W/125sxs cement  
 Port Collar @ 1401' cemented with 150sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

**RECEIVED  
 SEP 10 2012  
 KCC WICHITA**

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier  
*Michael Maier*

Retain 1 Copy District Office SEP - 6 2012  
 Send 1 Copy to Conservation Division

KCC DODGE CITY

Form: 02/22/2008

*YAM*

Date: 08/27/12

District: 01

License #: 4058

Op Name: 4058

Spot: SW-NW-NE-NW Sec 36 Twp 22 S Rng 23  E  W

County: Hodgeman

Lease Name: Hodgeman-O'brate Well #: 4-36

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21.822-00-00	332FNL 1648FWL	SW-NW-NE-NW	38.10094-99.80162	4-36	New well, Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008