




KANSAS CORPORATION COMMISSION
CONSERVATION DIVISION
130 S. MARKET - ROOM 2078
WICHITA, KS 67202

CLOSURE OF SURFACE POND

| | | | |
|--|---------------------------------------|--|---|
| OPERATOR NAME American Energies Corporation | | LICENSE NO. 5399 | |
| OPERATOR ADDRESS 155 North Market, Suite 710, Wichita, KS 67202 | | | |
| CONTACT PERSON Alan L. DeGood, President | | PHONE NUMBER (316) 263-5785 | |
| PERMIT NUMBER (API NO. IF APPLICABLE) 15-113-20586-0000 | | LEASE NAME Unruh (Orlando) B-3 | |
| TYPE OF POND: | | PIT LOCATION: | |
| <input type="checkbox"/> EMERGENCY PIT | <input type="checkbox"/> BURN PIT | SEC <u>23</u> TWP <u>21</u> RNG <u>2W</u> E/W | NW SW SW SE |
| <input type="checkbox"/> TREATMENT PIT | <input type="checkbox"/> DRILLING PIT | <u>340</u> FSL Ft. from N/S Line of Section. (circle one) | |
| <input checked="" type="checkbox"/> WORKOVER PIT | | <u>2322</u> FEL Ft. from E/W Line of Sec. (circle one) | |
| | | <u>McPherson</u> County | |
| Date of Closure: <u>11/14/2011</u> | | | |
| Was an artificial liner used? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | | |
| If no, how were the sides and bottom sealed to prevent downward migration of the pit contents: | | | |
| <u>Plastic liner was used to line the pit.</u> | | | |
| Abandonment procedure of pit: <u>All fluids were removed and taken to disposal well</u> | | | |
| The undersigned hereby certifies that he/she is <u>Alan L. DeGood, President</u> | | | RECEIVED DEC 08 2011 KCC WICHITA |
| for <u>American Energies Corporation</u> a duly authorized agent, that all information shown hereon is true and correct to the best of his knowledge and belief. | | | |
|  | |  Alan L. DeGood, President | |
| Subscribed and sworn to before me on this <u>7</u> th day of | | December <u>2011</u> | |
| My Commission Expires: 3-12-12 | |  Melinda S. Wooten, Notary Public | |