KANSAS CORPORATION COMMISSION CONSERVATION DIVISION 130 S. MARKET - ROOM 2078 WICHITA, KS 67202

CLOSURE OF SURFACE POND

OPERATOR NAME	LICENICS NO
American Energies Corporation	LICENSE NO. 5399
OPERATOR ADDRESS	
155 North Market, Suite 710, Wichita, KS 67202	· · · · · · · · · · · · · · · · · · ·
CONTACT PERSON	PHONE NUMBER
Alan L. DeGood, President	(316) 263-5785
PERMIT NUMBER (API NO. IF APPLICABLE)	LEASE NAME
15-095-20646 3000	A. E. Greenleaf OWWO #1
TYPE OF POND:	PIT LOCATION: C NE/4
111 E 0. 1 ONO.	THEODATION. CHEM
	N PIT SEC <u>13</u> TWP <u>28</u> RNG <u>7W</u> E/W
TREATMENT PIT DRILI X WORKOVER PIT	LING PIT
WORKOVER FII	1320 FNL Ft. from N/S Line of Section. (circle one)
	1320 FEL Ft. from E/W Line of Sec.
	(circle one)
	Kingman County
	· · · · · · · · · · · · · · · · · · ·
Date of Closure: 1/10/2012	<u> </u>
Date of Closure: 1/10/2012 Was an artificial liner used? X Yes	 No
Was an artificial liner used? X Yes	
Was an artificial liner used? X Yes	
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prev	vent downward migration of the pit contents:
Was an artificial liner used? X Yes f no, how were the sides and bottom sealed to prev ML Plastic Liner used, liner removed, fluids hauler	
Was an artificial liner used? X Yes f no, how were the sides and bottom sealed to prev ML Plastic Liner used, liner removed, fluids hauler	vent downward migration of the pit contents:
Was an artificial liner used? X Yes f no, how were the sides and bottom sealed to prev ML Plastic Liner used, liner removed, fluids hauter Restored to natural locaton.	vent downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil.
Was an artificial liner used? X Yes f no, how were the sides and bottom sealed to prev ML Plastic Liner used, liner removed, fluids hauter Restored to natural locaton.	vent downward migration of the pit contents:
Was an artificial liner used? X Yes f no, how were the sides and bottom sealed to prev ML Plastic Liner used, liner removed, fluids hauter Restored to natural locaton.	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition.
Was an artificial liner used? X Yes f no, how were the sides and bottom sealed to prev ML Plastic Liner used, liner removed, fluids hauter Restored to natural locaton.	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition.
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sealed to prevent of	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sides and sides a	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12 Alan L. DeGood, President
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sides and sides a	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12 Alan L. DeGood, President y authorized agent, that all information shown hereon belief.
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sides and the sides and sides and the side	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12 Alan L. DeGood, President y authorized agent, that all information shown hereon belief.
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sealed to prevent of	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12 Alan L. DeGood, President y authorized agent, that all information shown hereon belief. Olan C De Jan
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sides and the sides and sides and the side	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12 Alan L. DeGood, President y authorized agent, that all information shown hereon belief.
Was an artificial liner used? X Yes If no, how were the sides and bottom sealed to prevent of the sealed to prevent of	went downward migration of the pit contents: d to disposal well, pit backfilled with natural clay and soil. s hauled, liner removed, restored to natural condition. RECEIV JAN 12 Alan L. DeGood, President y authorized agent, that all information shown hereon belief. Olan C De Jan
Was an artificial liner used? If no, how were the sides and bottom sealed to prevent of the state of the sides and bottom sealed to prevent of the state of the sides and bottom sealed to prevent of the state of t	Alan L. DeGood, President Alan L. DeGood, President y authorized agent, that all information shown hereon belief. Alan L. DeGood, President Alan L. DeGood, President Alan L. DeGood, President Alan L. DeGood, President
Was an artificial liner used? If no, how were the sides and bottom sealed to prevent of the state of the sides and bottom sealed to prevent of the state of the sides and bottom sealed to prevent of the state of t	Alan L. DeGood, President Alan L. DeGood, President y authorized agent, that all information shown hereon belief. Alan L. DeGood, President Alan L. DeGood, President Alan L. DeGood, President Alan L. DeGood, President