		API NUMBER 15-	
To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202 TECHNICIAN'S PLUGGING REPORT Operator License # 6867		SW SW SW , SEC.	14 , 7 16 S, R 16 W,
			feet from S section 11
			
		4950 feet from E section ii	
		Lease Name Schippers Well 1 1	
	LaVern Steinle	County	Rush 115.67
Name& Address	624 East 3rd	Well Total Dept	thfe
	Russell, KS 67665	Conductor Pipe:	: \$1ze 15 1/2 feet 21
		Surface Casing:	: Size 12 1/2 feet 485
Abandoned	Oll Well X Gas Well	Input Well	SWD WellD&A
Other wel	t as hereinafter indicated		
Pluaalna	Contractor Allied Cementing		License Number
	Box 31, Russell, KS 67665		
	o plug at: Hour: 9:00 am Day:	19 Month:	June Year:19 85
	proposal received from		
Plugging	proposal received from		,_, ,012 /02_200
(company	name) LaVern Steinle		
			2650 6 20 60 7H 14mam
fro	at 1054', 8 5/8" at 2835', 7" as m 820' to surface - circulated, as tota at 300', Cement from 3538-35	Anhydrite at 1075',	Cedar Hills at 550', Base
fro Dak	at 1054', 8 5/8" at 2835', 7" as mm 820' to surface - circulated, as tota at 300', Cement from 3538-35; 1/2"-8 5/8" annulus squeezed the	Anhydrite at 1075', 23, bit and collar	Cedar Hills at 550', Base at approx, 2500'
fro Dak 1981- 12	om 820' to surface - circulated, a cota at 300', Cement from 3538-35	Anhydrite at 1075', 23, bit and collar	Cedar Hills at 550', Base at approx, 2500'
fro Dak 1981- 12	om 820' to surface - circulated, acta at 300', Cement from 3538-35; 2 1/2"-8 5/8" annulus squeezed the	Anhydrite at 1075', 23, bit and collar ree times with 325	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole
fro Dak 1981- 12	om 820' to surface - circulated, acta at 300'. Cement from 3538-352 1/2"-8 5/8" annulus squeezed the color and circulated to surface. - pumped 200 sx cement down 7" as	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up
fro Dak 1981- 12	om 820' to surface - circulated, acta at 300'. Cement from 3538-352 1/2"-8 5/8" annulus squeezed the color and circulated to surface. - pumped 200 sx cement down 7" as	Anhydrite at 1075', 23, bit and collar ree times with 325	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up
fro Dak 1981- 12 82 6-19-85	om 820' to surface - circulated, acta at 300'. Cement from 3538-352 1/2"-8 5/8" annulus squeezed the color and circulated to surface. - pumped 200 sx cement down 7" as	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN)
fro Dak 1981- 12 82 6-19-85	om 820' to surface - circulated, Acta at 300', Cement from 3538-352 1/2"-8 5/8" annulus squeezed the control of	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN)
fro Dak 1981- 12 82 6-19-85 Plugging Operation	om 820' to surface - circulated, acta at 300'. Cement from 3538-35: 2 1/2"-8 5/8" annulus squeezed the control of the control	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL	om 820' to surface - circulated, acta at 300', Cement from 3538-352 1/2"-8 5/8" annulus squeezed the control of	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part 19 Month:	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year:19 85
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"-	om 820' to surface - circulated, acta at 300', Cement from 3538-35; 2 1/2"-8 5/8" annulus squeezed the 20' and circulated to surface. - pumped 200 sx cement down 7" as Plugging Pro Operations attended by Agent?: as Completed: Hour: 11:30 ampay: UGGING REPORT CONTINUED - -8 5/8" annulus with immediate pro-	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part 19 Month:	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year:19 85
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"-	om 820' to surface - circulated, acta at 300', Cement from 3538-352 1/2"-8 5/8" annulus squeezed the control of	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part 19 Month:	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year:19 85
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"-	om 820' to surface - circulated, acta at 300', Cement from 3538-35; 2 1/2"-8 5/8" annulus squeezed the 20' and circulated to surface. - pumped 200 sx cement down 7" as Plugging Pro Operations attended by Agent?: as Completed: Hour: 11:30 ampay: UGGING REPORT CONTINUED - -8 5/8" annulus with immediate pro-	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part 19 Month:	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85 lays and fill 7" from 300'
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"-	om 820' to surface - circulated, acta at 300', Cement from 3538-35; 2 1/2"-8 5/8" annulus squeezed the 20' and circulated to surface. - pumped 200 sx cement down 7" as Plugging Pro Operations attended by Agent?: as Completed: Hour: 11:30 ampay: UGGING REPORT CONTINUED - -8 5/8" annulus with immediate pro-	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part 19 Month:	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"-	om 820' to surface - circulated, acta at 300', Cement from 3538-35; 2 1/2"-8 5/8" annulus squeezed the 20' and circulated to surface. - pumped 200 sx cement down 7" as Plugging Pro Operations attended by Agent?: as Completed: Hour: 11:30 ampay: UGGING REPORT CONTINUED - -8 5/8" annulus with immediate pro-	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All X Part 19 Month:	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85 lays and fill 7" from 300'
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"- to surfa	om 820' to surface - circulated, acta at 300'. Cement from 3538-35: 2 1/2"-8 5/8" annulus squeezed the control of the control	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by Ait X Part 19 Month: essure. Wait two d	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85 JUN 2 1 1955 Grand Steve Dury 2 1 1955
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"- to surfa	om 820' to surface - circulated, acta at 300'. Cement from 3538-35: 2 1/2"-8 5/8" annulus squeezed the color and circulated to surface. - pumped 200 sx cement down 7" and Plugging Pro Operations attended by Agent?: as Completed: Hour: 11:30 ampay: UGGING REPORT CONTINUED - -8 5/8" annulus with immediate proceed with cement. No recovery. Used 60/40 Pozmix 6 (if additional description is	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by Ait X Part 19 Month: essure. Wait two d	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85 JUN 2 1 1955 Grand Steve Dury 2 1 1955
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"- to surfa Remarks:	om 820' to surface - circulated, acta at 300', Cement from 3538-35: 2 1/2"-8 5/8" annulus squeezed the continued to surface. - pumped 200 sx cement down 7" and pum	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by All All Annual Month: Sesure. Wait two descriptions of the sesure wait two descriptions of the sesure was a second of the session was a second of the session was a second of the session was a second of the second of the session was a second of the session was a second of the session was a second of the second of t	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85 JUN 2 1 1955 Grand Andreas JUN 2 1 1955
fro Dak 1981- 12 82 6-19-85 Plugging Operation ACTUAL PL 12 1/2"- to surfa Remarks:	om 820' to surface - circulated, acta at 300'. Cement from 3538-35: 2 1/2"-8 5/8" annulus squeezed the color and circulated to surface. - pumped 200 sx cement down 7" and Plugging Pro Operations attended by Agent?: as Completed: Hour: 11:30 ampay: UGGING REPORT CONTINUED - -8 5/8" annulus with immediate proceed with cement. No recovery. Used 60/40 Pozmix 6 (if additional description is	Anhydrite at 1075', 23, bit and collar ree times with 325 and fell to 300' in posal Received by Ait X Part 19 Month: essure. Wait two d	Cedar Hills at 550', Base at approx. 2500' sx cement, 7" ran in hole 2 hours. Pressured up Steve Durrant (TECHNICIAN) None June Year: 19 85 JUN 2 1 1955 Grand State S