## KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/12/12</u>	District: <u>01</u>				
<del></del>	New Situation Lease Inspection				
	Response to Request Complaint				
	Follow-Up Field Report				
Operator License No: 4058	API Well Number: <u>15-135-25,458-00-00</u>				
Op Name: American Warrior	Spot: SW-NW-SE-NE Sec 24 Twp 19 S Rng 22 E / W				
Address 1: P.O. Box 399	1770 (1804) Feet from N/ S Line of Section				
Address 2:	1115 (1114) Feet from Feet from E/ W Line of Section				
City: Garden City	GPS: Lat: 38.38796 Long: 99.69994 Date: 9/12/12				
State: Kansas Zip Code: <u>67846 -0399</u>	Lease Name: Schaben Well #: 4-24				
Operator Phone #:	County: Ness				
Reason for Investigation:					
Witness Alt.II					
Problem:					
None, cement circulated to surface					
Persons Contacted:					
Findings.					
Findings:					
8-5/8" @ 224W/150sxs cement					
TD @ 4346'					
5-1/2" @ 4345'W/145sxs cement Port Collar @ 1431' cemented with 115sxs-s	md-1/4# flo seal-2%cc-10sxs went to pit				
For Conar & 1451 Cernence with 1100x0 5	ma 17 17 no obar 27000 trone trone to pro				
	,				
Follow To the Control of the Control	w Up Required Yes No 🔊 Date:				
	RECEIVED				
Alt.II requirements have been met					
	SEP 2 7 2012				
	KCC WICHITA				
Verification Sources:	Photos Taken:				
RBDMS KGS	TA Program				
	Courthouse By: Michael Majer				
Other:					
Retain 1 Copy District Office RECEIVED					
Send I Copy to Conservation Division	Form: 02/22/2008				
SEP <b>2 1</b> 2012	Tom. VEIELICOU				

AND

Date: <u>09/12/12</u>	<u></u>	<u></u>	District	: <u>01</u>	I	License #: 4058	
Op Name: 4058				pot: <u>SW-NW-SE-NE</u> Sec <u>24</u> Twp <u>19</u> S Rng <u>22</u> E			
County: Ness				ase Name: Schaben Well #: 4-24			
I.D. Sign Yes	No		<u> </u>	Γ	Yes No	រា	
Tank Battery Condition: Good		ible Overflor	wing	Pits Fluid Depth:	ft; Approx.	Size:ft. xft.	
Pits, Injection Site		Size:t	ft. xft.	Saltwater Leaks Visib	Pipelines	Tested for Leaks: Y N	
Oil Spill Evidence				Flowing H	oles		
Abandoned Well	Potential Poll	lution Problem [	Yes No ST	TA Wells			
Lease Cleanliness Very Good S	atisfactory [	Poor Ver	y Bad	Monitorin	g Records		
SWD/ER Injection Well           Permit #:         P           Permit #:         P           Permit #:         P           Permit #:         P	Yes ressure – Acturessure – Actures – Actu	No	Ness psi thorized: psi thorized: psi	Tubing: Tubing: Tubing:	; T/C Annulus: _ ; T/C Annulus: _	; C/SP Annulus: ; C/SP Annulus: ; C/SP Annulus: ; C/SP Annulus:	
API Number	Footages	Spot Location	GPS	Well#		Well Status	
<u>15-135-25,458-00-00</u>	1805FNL 1114FEL	SW-NW-SE-NE	38.38796-99.699	994 4-24	New well, Alt.II c	ompleted	
		_					