KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/26/12</u>	District: 01	Case #:	
	New Situation	Lease Inspection	
	Response to Request	Complaint	
	Follow-Up	Field Report	
		<u> </u>	
Operator License No: 34318	API Well Number: <u>15-083</u>	3-21842-00-00	
Op Name: Berexco LLC	Spot: <u>NE NW SW NE</u>	_Sec <u>17 </u>	<u>:1</u>
Address 1: 2020 N Bramblewood		Feet from N/	
Address 2:	•	Feet from F	
City: Wichita	GPS: Lat: <u>38.05381</u>		9/26/12
State: Kansas Zip Code: 67206 -1094		Well #:	1-17
Operator Phone #: (316) 265-3311	•		
Reason for Investigation:			
Company request witness for alternate 2 con	npietion.		
Problem:			
None			
Persons Contacted:		· · · · · · · · · · · · · · · · · · ·	
None			
Findings:		***	
8 5/8" set at 300' with 200sx cmt.			İ
5 1/2" set at 5167' with 325 sx cmt.			
TD at 5347'			RECEIVED
DVT 1 144001 W 050 1 0011111	• 4		
DV Tool at 1493' with 350sx cmt, 20bbls to p	IT.	i	OCT 1 1 2012
Used 60/40pox 8% gel 1/4# flo seal by Consolidated Oil Well Services.			
Used 60/40pox 8% get 1/4# flo seal by Consolidated Oil Well Services. KCC WICHITA			
Action/Recommendations: Follow	v Up Required Yes ✓ No	Date:	
	· op Acquires		
Alternate 2 cementing requirements fulfilled.			
			İ
Verification Sources:		Photos 7	Гакеп:
RBDMS KGS	ΓA Program		
	Courthouse By: Den	el Bernasconi	
Other:		weit Semuser	
Retain 1 Copy District Office HEULIVED		_	
Send 1 Copy to Conservation Division		Form:	
0CT - 5 2012 X			

KCC DODGE CITY

RNX