

# KCC OIL/GAS REGULATORY OFFICES

Date: 10/16/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 9408

API Well Number: 15-135-25,486-00-00

Op Name: Trans Pacific Oil Corporation

Spot: NE-NW-SE-SW Sec 12 Twp 20 S Rng 22  E /  W

Address 1: 100 S Main Ste 200

1178 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

1965 Feet from  E /  W Line of Section

City: Wichita

GPS: Lat: 38.32330 Long: 99.70690 Date: 10/16/12

State: Kansas Zip Code: 67202 -3735

Lease Name: Schaben 'A' Unit Well #: 1-12

Operator Phone #: (316) 262-3596

County: Ness

### Reason for Investigation:

Witness Alt. II

### Problem:

None

### Persons Contacted:

\_\_\_\_\_

### Findings:

8-5/8" @ 220'W/150sxs  
TD @ 4393'  
5-1/2" @ 4387'W/145sxs  
Port Collar @ 1426' cemented with 140sxs-smd-1/4# flo seal-2%cc-20sxs to pit.

### Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt. II requirements have been met.

### Verification Sources:

Photos Taken: 0

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

By: Michael Maier  
Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

OCT 19 2012

KCC DODGE CITY

RECEIVED

RECEIVED

OCT 25 2012

KCC WICHITA

Form: 02/22/2008

AMV

Date: 10/16/12

District: 01

License #: 9408

Op Name: 9408

Spot: NE-NW-SE-SW Sec 12 Twp 20 S Rng 22  E  W

County: Ness

Lease Name: Schaben 'A' Unit Well #: 1-12

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.486-00-00	1159FSL 1982FEL	NE-NW-SE-SW	38.32330-99.70690	1-12	New well. Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division