

KCC OIL/GAS REGULATORY OFFICES

Date: 11/09/12

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5144
 Op Name: Mull Drilling Company, Inc.
 Address 1: 1700 N Waterfront Pkwy
 Address 2: Bldg. 1200
 City: Wichita
 State: Kansas Zip Code: 67206 -6637
 Operator Phone #: (316) 264-6365

API Well Number: 15-135-25,151-00.01
 Spot: NW-SW-NW-SE Sec 30 Twp 16 S Rng 22 E / W
 1778 (1785) Feet from N / S Line of Section
 2580 (2555) Feet from E / W Line of Section
 GPS: Lat: 38.63018 Long: 99.79935 Date: 11/9/12
 Lease Name: Jones Unit OWWO Well #: 1-30
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 217' W/165sxs cement
 TD @ 4524'
 5-1/2" @ 4514' W/150sxs cement
 Port Collar @ 1623' cement with 160sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt.II requirements have been met.

RECEIVED
 KANSAS CORPORATION COMMISSION
 NOV 21 2012
 CONSERVATION DIVISION
 WICHITA, KS

Verification Sources:

Photos Taken: _____

<input type="checkbox"/> RBDMS	<input checked="" type="checkbox"/> KGS District Files	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database		<input type="checkbox"/> Courthouse
Other: _____		

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

KCC DODGE CITY

Form: 02/22/2008

AMT

Date: 11/09/12

District: 01

License #: 5144

Op Name: 5144

Spot: NW-SW-NW-SE Sec 30 Twp 16 S Rng 22 E W

County: Ness

Lease Name: Jones Unit OWWO Well #: 1-30

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness

Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.151-00-01	1785FSL 2555FEL	NW-SW-NW-SE	38.63018-99.79935	1-30	New well, Alt. II completed