

KCC OIL/GAS REGULATORY OFFICES

Date: 11-6-12

District: 1

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 3842  
 Op Name: Larson Engineering (Larson)  
 Address 1: 562 W. State Rd 4  
 Address 2: \_\_\_\_\_  
 City: Olmita  
 State: KS Zip Code: 67564  
 Operator Phone #: 620 653-7368

API Well Number: 15-101-22405-0000  
 Spot: SE SW SW Sec 17 Twp 19 S Rng 20  E /  W  
 Feet from  N /  S Line of Section  
462  
 Feet from  E /  W Line of Section  
847  
 GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: \_\_\_\_\_  
 Lease Name: Helen Well #: 3-17  
 County: Lane

Reason for Investigation:

Alternate II Cementing

Problem:

\_\_\_\_\_

Persons Contacted:

\_\_\_\_\_

Findings:

8 7/8" @ 261' ; 5 1/2" @ 4704 w/ 1253x Port Collar @ 2085'  
Swift Sucs pumped 2355x SMD thru port collar, Circulated  
205x to the pit.

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alternate II Cementing Complete.

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- FA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Ken Schlik

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED

NOV - 9 2012

KCC DODGE CITY

RECEIVED

NOV 14 2012

KCC WICHITA

Form: \_\_\_\_\_

*Handwritten initials*

Date: \_\_\_\_\_

District: \_\_\_\_\_

License #: \_\_\_\_\_

Op Name: \_\_\_\_\_

Spot: \_\_\_\_\_ Sec \_\_\_\_\_ Twp \_\_\_\_\_ S Rng \_\_\_\_\_  E  W

County: \_\_\_\_\_

Lease Name: \_\_\_\_\_ Well #: \_\_\_\_\_

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness

Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines

Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_