

# KCC OIL/GAS REGULATORY OFFICES

Date: 12/27/12

District: 01

Case #: \_\_\_\_\_

- New Situation  
 Response to Request  
 Follow-Up

- Lease Inspection  
 Complaint  
 Field Report

Operator License No: 4058

API Well Number: 15-135-25.5|1-00-00

Op Name: American Warrior

Spot: NE-SW-SE-SE Sec 8 Twp 19 S Rng 21  E /  W

Address 1: P.O. Box 399

471 (457) Feet from  N /  S Line of Section

Address 2: P.O. Box 783188

987 (968) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.40888 Long: 99.66279 Date: 12/27/12

State: Kansas Zip Code: 67846 -0399

Lease Name: Stieben A Well #: 6

Operator Phone #: (620) 587-3224

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 222'W/150sxs cement  
TD @ 4296'  
5-1/2" @ 4295'W/175sxs cement  
Port Collar @ 1370' cemented with 130sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

Verification Sources:

Photos Taken: 0

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
Other: _____		

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

JAN - 9 2013

KCC DODGE CITY

By: Michael Majer

RECEIVED

JAN 14 2013

KCC WICHITA

Form: 02/22/2008

Date: 12/27/12

District: 01

License #: 4058

Op Name: 4058

Spot: NE-SW-SE-SE Sec 8 Twp 19 S Rng 21  E  W

County: Ness

Lease Name: Stieben A Well #: 6

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25,551-00-00	457FSL 968FEL	NE-SW-SE-SE	38.40888-99.66279	6	New well, Alt. II completed