

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION SE-NE-NW

SEC. 2 TWP. 18 RGE. 17W

Dry Hole ✓ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Robison armita

Operator Pan American Petro Corp Address Box 7 Ellinwood Kansas

Field _____ County Rush

Total Depth 3536 Feet.

Plugging Contractor Prime Hrg. Co

Plugging Contractor's License No. _____

Address 814 Union Center Wichita Kansas

(Describe Briefly the manner in which the well was plugged)

Surf Pipe 8 5/8 @ 1.070 c.w. 600 sq. ft.
Plugged with hole full of Well Mud to
400 feet and 3/4 sq. ft. Halls and Plug and
35 sq. ft. Cement Pumped Through Drill Pipe
with H.P. Pump truck and Well Mud
to 20 feet and 3/4 sq. ft. Halls and 3' sq. ft.
Cement to the base of the collar

Ron Ruediger
District Conservation Agent

Date 8-3-1957

PLUGGING
FILE SEC. 2 T. 18 R. 17W
BOOK PAGE 34 LINE 10