

DISTRICT CONSERVATION AGENT'S REPORT

R

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION SW-SW-NE

SEC. 12 TWP. 18 RGE. 17W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Crotinger

Operator Victor Drly. Co. Address 301 Koch Bldg Wichita, Ks.

Field _____ County Rush

Total Depth 3558 Feet.

Plugging Contractor Victor Drly. Co.

Plugging Contractor's License No. _____

Address 301 Koch Bldg, Wichita, Kans.

(Describe briefly the manner in which the well was plugged)

Surface Pipe 8" @ 869' C.W.C. Hole leaking water
as drill pipe was laid down. Had out Halliburton
Cem. Co. and tied on to surface casing and
squeezed well with 500 SK of Cem. filling hole &
Surface casing from approx 1500' to surface with
Cem.

PLUGGING
FILE SEC 12 T 18 R 17W
BOOK PAGE 4 LINE 5

Warren H. Warner
District Conservation Agent

12-28-53

Date 12-24-53