

19

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. 47-1

LOCATION SE-SE

SEC. 24 TWP. 18 RGE. 16-W

Dry Hole _____ Abandoned Oil Well _____ Abandoned Gas Well X

I have today completed supervision of plugging of:

Well No. 1 Lease Wm. Rubart

Operator Thygeson Oil Co Address #813 - Thompson Bldg - Tulsa - Okla

Field _____ County Push

Total Depth 3543 Feet.

(Describe briefly the manner in which the well was plugged)

Surface Pipe - 1 1/2" - 226ft - Circulated with cement
10" casing - 927ft - Circulated with cement -
7" casing set at 3533ft & cemented with 425 sacks of cement -
dumped 15 sacks of cement on bottom of hole - shot off
& pulled 7" casing - set bridge at 875ft & filled the
10" casing from 875ft to the surface with cement.
Run in by Halliburton Oil Well Cementing Co
350 Sacks of cement used -
J. Aylward - Pipe Pulling
Contractor
C. M. Stovish
District Conservation Agent

Date 10-11-48

NOV 13 1948
10-13-48

