

## District Plugging Report

Operator License No: 101	String	Size	Depth	Pulled	Comments
Op Name: KANSAS CORPORATION COMMISSION					
Address 1: 130 S MARKET					
Address 2:					
City: WICHITA					
State: KS Zip Code: 67202 -					

Proposed Plugging Report:	OF CASING. IF CEMENT IS PRESENT IN THE ANNULUS, CASING SHOULD BE PERFORATED IN AT LEAST 2 INTERVALS, UNLESS WELL IS DOCUMENTED AS ALT. 2 COMPLETION.
---------------------------------	--

**Plugging Proposal Received By:** TOM BILYEU/TONY ANDERSON      **Witness Type:** COMP - Complete 100%

**Date/Time Plugging Completed:** 11/16/12 / \_\_\_\_\_      **KCC Agent:** TOM BILYEU/TONY ANDERSON

**Actual Plugging Report:**      **Perfs:**      **Top**      **Bottom**      **Thru**

DIG UP AREA TO FIND BOREHOLE. SET 23' OF SURFACE. DRAIN POND AND HAUL IN ROCK TO BUILD LOCATION. HAD TROUBLE WITH WASHING OUT UNDER THE RIG, ADDED DRILLING MUD. DRILLED TO 150' AND WASHED 1" TO 450'. PUMPED 224 SACKS OF CEMENT TO SURFACE. THE LANDOWNER DID NOT REQUEST THAT THE ROCK BE REMOVED. THE DRILL PIT WAS EMPTIED AND BACKFILLED.

~~KANSAS CORPORATION COMMISSION~~

~~JAN 04 2013~~

RECEIVED

Remarks	CONTRACT 11782; CONTROL#20130037-001; GPS IN NAD 83
---------	---

Plugged Thru: Tubing

Plugged Due to Compliance Issue: ☐ Yes ☐ No

**District: 03**

**(Technician)**

Form: District Plugging Report –