

District Plugging Report

Operator License No: <u>101</u>	String	Size	Depth	Pulled	Comments
Op Name: <u>KANSAS CORPORATION COMMISSION</u>	<u>SURF - Casing</u>	<u>8.000</u>			
Address 1: <u>130 S MARKET</u>	<u>T1 - Tubing 1</u>	<u>2.000</u>			
Address 2: _____					
City: <u>WICHITA</u>					
State: <u>KS</u> Zip Code: <u>67202</u> <u>-</u>					

Proposed Plugging Report:

CLEAN OUT WELLS TO BOTTOM. PUMP FULL OF PORTLAND CEMENT, INSIDE AND OUTSIDE OF CASING. IF CEMENT IS PRESENT IN THE ANNULUS, CASING SHOULD BE PERFORATED IN AT LEAST 2 INTERVALS, UNLESS WELL IS DOCUMENTED AS ALT. 2 COMPLETION.

CLEAR AREA AROUND WELLS. WASH 500' INSIDE AND 400' OUTSIDE. PUMPED 147 SACKS OF CEMENT. THE LOCATION WAS THEN RESTORED.

KANSAS CORPORATION COMMISSION
NOV 02 2012
RECEIVED

Remarks	CONTRACT#11782;CONTROL#20130003-003; regular section
---------	------------------------------------------------------

Plugged Thru: _____

Plugged Due to Compliance Issue: ☐ Yes ☐ No**District: 03**

(Technician)

Form: District Plugging Report –