

District Plugging Report

Operator License No: 101	String	Size	Depth	Pulled	Comments
Op Name: STATE OF KANSAS	SURF - Casing	8.000		0	
Address 1: 130 S MARKET	COND - Conductor Pipe	12.000		0	
Address 2:	T1 - Tubing 1	1.000	940	940	ON PACKER
City: WICHITA	PROD - Casing	1000.000		0	
State: KS Zip Code: 67202					

**Proposed
Plugging
Report:**

CLEAN WELL TO BOTTOM. PUMP FULL OF PORTLAND CEMENT INSIDE AND OUTSIDE OF CASING. IF CEMENT IS PRESENT IN THE ANNULUS THE CASING SHOULD BE PERFORATED IN AT LEAST 2 INTERVALS, UNLESS DOCUMENTED AN ALT2 COMPLETION.

PULLED 940' OF 1" ON PACKER FROM INSIDE OF 2" PIPE. RAN DOWN OUTSIDE OF 2" TO 900'. TORCHED HOLE IN 10" SURFACE AND FOUND 8" PIPE. PERFED AND RAN PIPE BACK IN 1100' INSIDE AND 900' OUTSIDE. PUMPED 222 SACKS OF CEMENT. THE LOCATION WAS THEN RESTORED.

[illegible]

Remarks	CONTRACT#EVT0000981; CONTROL#20120009-005 ; NAD27
---------	---

Plugged Due to Compliance Issue: ☐ Yes ☒ No

Thomas Bilzer
(Technician)

Form: District Plugging Report -