

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION NE-SW-22W

SEC. 30 TWP. 18 RGE. 31-40

Dry Hole X Abandoned Oil well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Chance "A"

Operator Herndon Dely Co Address 423 Mayo Bldg. Tulsa, Okla

Field _____ County Scott

Total Depth 5106 Feet.

Plugging Contractor Herndon Dely Co.

Plugging Contractor's License No. _____

Address _____

(Describe briefly the manner in which the well was plugged)

Surface Pipe 8 3/8 - 271 ft. Circulated with cement
Hole full of heavy mud. Set Plug &
15 sacks of cement at 260 ft. through the
Drill Pipe - mud to 20 ft. Plug & 10 sacks
of cement at the surface.

RECEIVED
STATE CONSERVATION

C. H. Stough -
District Conservation Agent

Date 8-26-53

PLUGGING
FILE SEC 30 T 18 R 31W
BOOK PAGE 125 LINE 16

8-28-53