

KCC OIL/GAS REGULATORY OFFICES

Date: 7-17-13

District: 1

Case #: \_\_\_\_\_

New Situation

Lease Inspection

Response to Request

Complaint

Follow-Up

Field Report

Operator License No: 7311

API Well Number: 15-171-20956-00-00

Op Name: Shakespeare Oil Co. Inc

Spot: NE SE NE Sec 34 Twp 16 S Rng 34  E /  W

Address 1: 202 W. Main St

1363 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

339 Feet from  E /  W Line of Section

City: Salem

GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: \_\_\_\_\_

State: IL Zip Code: 62881-

Lease Name: Janzen Well #: 1-34

Operator Phone #: 618 548-1585

County: Scott

Reason for Investigation:

Alternate II Cementing

Problem:

\_\_\_\_\_

Persons Contacted:

\_\_\_\_\_

Findings:

8 3/8" 2 1/4" w/ 175sx; 5 1/2" 4891' w/ 150sx; Port collar @ 2405'; TD-4893'  
Alheid pumped 385sx 65/35 pr 8% gel @ 600# huls thru port collar @ 2405'. Circ 30sx to the pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alternate II Cementing Complete.

**KCC WICHITA**  
**JUL 29 2013**  
**RECEIVED**

Verification Sources:

RBDMS  KGS  TA Program  
 T-I Database  District Files  Courthouse  
 Other: \_\_\_\_\_

Photos Taken: \_\_\_\_\_

By: Ken Sehlke

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**RECEIVED**  
**JUL 24 2013**

**KCC DODGE CITY**

Form: \_\_\_\_\_

*Ray*

Date: \_\_\_\_\_

District: \_\_\_\_\_

License #: \_\_\_\_\_

Op Name: \_\_\_\_\_

Spot: \_\_\_\_\_ Sec \_\_\_\_\_ Twp \_\_\_\_\_ S Rng \_\_\_\_\_  E  W

County: \_\_\_\_\_

Lease Name: \_\_\_\_\_ Well #: \_\_\_\_\_

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_