KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/18/13</u>	District: 1	Case #:
	New Situation	Lease Inspection
	Response to Request	Complaint
	Follow-Up	Field Report
Operator License No: 4767	API Well Number: 15-0	
Op Name: Ritchie Exploration, Inc.		Sec 11 Twp 28 S Rng 23 E / W
Address 1: Box 783188		Feet from N/ S Line of Section
Address 2:		Feet from E/W Line of Section
City: Wichita		Long: 99.81091Date: 7/18/13
State: KS Zip Code: 67278 -3188		Well #: _1
Operator Phone #: (316) 691-9500	County: Ford	
Reason for Investigation:		
Company requested a state witness to the alternate II cementing job.		
Problem:		
Alternate II cementing requirements have not been met.		
Persons Contacted:		
None.		
Findings:		
8 5/8" was set @ 364' with 250 sx cement. 5 1/2" was set @ 5207' with 250 sx cement on the primary		
cementing job. Company opened the port collar @ 1388' Consolidated Oil Well Services, L.L.C. pumped		
290 sx cement, circulating 20 sx to the pit. Cl	osed the port collar.	
Action/Recommendations: Follow	Up Required Yes V	No 🔽 Date:
None. Alternate II cementing requirements h	ave been met.	
60/40 pozmix, 6% gel, 1/4# floseal by Consolidated Oil Well Services, L.L.C.		
00/40 pozifiix, 6 % gei, 1/4# iloseal by Collson	idated Oil Well Servic	JUL 2 9 2013
GPS converted footages are 1687' FNL & 100	01' FWL.	JOL 2 3 2013
		RECEIVED
Verification Sources:		Photos Taken: <u>()</u>
RBDMS KGS T	A Program	in Myh
T-I Database	ourmouse	
Other: On-site witness.	<u>E</u> ri	c MacLaren
Retain I Copy District Office RECEIVED		
Send 1 Copy to Conservation Division JUL 2 4 2013		Form:
2012 M		
KCC DODGE CITY		.ΩΛn