

KCC OIL/GAS REGULATORY OFFICES

Date: 06/25/13

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
 Op Name: American Warrior Inc.  
 Address 1: 3118 Cummings Rd  
 Address 2: P.O. Box 399  
 City: Garden City  
 State: Kansas Zip Code: 67846 -  
 Operator Phone #: (620) 275-2963

API Well Number: 15-083-21,885-00-00  
 Spot: NESWSWSE Sec 5 Twp 24 S Rng 21  E /  W  
 335 (324) Feet from  N /  S Line of Section  
 2039 (2408) Feet from  E /  W Line of Section  
 GPS: Lat: 37.42411 Long: 99.70487 Date: 6/25/13  
 Lease Name: Helfrich Well #: 6-6  
 County: Hodgeman

Reason for Investigation:

Witness Alt.li

Problem:

None

Persons Contacted:

Findings:

8-5/8"@280'W/175sxs  
 TD@4672'  
 5-1/2"@4667'W/125sxs  
 Port Collar@1439'W/120sxs-smd-1/4# floseal-2%cc-15sxs to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

KCC WICHITA  
 JUL 05 2013  
 RECEIVED

Verification Sources:

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

Photos Taken: \_\_\_\_\_

By: Michael Maier  
 Michael Maier

Retain 1 Copy District Office  
 Send 1 Copy to Conservation Division

JUL - 1 2013  
 KCC DODGE CITY

Form: \_\_\_\_\_

*MK*

Date: 06/25/13

District: 01

License #: 4058

Op Name: 4058

Spot: NESWSWSE Sec 5 Twp 24 S Rng 21  E  W

County: Hodgeman

Lease Name: Helfrich Well #: 6-6

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21,885-00-00	324FSL 2053FEL	NESWSWSE	37.98671-99.64989	6-5	Alt. II completed cement circulated to surface.

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_