

# KCC OIL/GAS REGULATORY OFFICES

Date: 07/31/13

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-25638-00-00

Op Name: American Warrior, Inc.

Spot: N2SWSWSE Sec 13 Twp 20 S Rng 21  E /  W

Address 1: 3118 Cummings Rd.

335 (338) Feet from  N /  S Line of Section

Address 2: P.O. Box 399

2310 2296 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.30671 Long: 99.59259 Date: 7/31/13

State: Kansas Zip Code: 67846

Lease Name: Felder ~~Felder~~ Well #: 2-13

Operator Phone #: (785) 398-2270

County: Ness

### Reason for Investigation:

Witness Alt.II

### Problem:

None

### Persons Contacted:

### Findings:

8-5/8"@225'W/150sxs  
TD@4397'  
5-1/2"@4396'W/175sxs  
Port Collar@1403'W/145sxs-smd-1/4#floseal-2%cc-15sxs to pit.

RECEIVED  
KANSAS CORPORATION COMMISSION

AUG 14 2013

CONSERVATION DIVISION  
WICHITA, KS

### Action/Recommendations:

Follow Up Required  Yes  No  ?

Date: \_\_\_\_\_

None-Alt.II requirements have been met.

### Verification Sources:

- |                                       |  |                                     |
|---------------------------------------|--|-------------------------------------|
| <input type="checkbox"/> RBDMS        | <input type="checkbox"/> KGS                       | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ |  |                                     |

Photos Taken: 0

By: Michael Maier

Michael maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED

AUG 12 2013

KCC DODGE CITY

Form: \_\_\_\_\_

Date: 07/31/13

District: 01

License #: 4058

Op Name: 4058

Spot: N2SWSWSE Sec 13 Twp 20 S Rng 21  E  W

County: Ness

Lease Name: Fedler Well #: 2-13

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25638-00-00	338FSL 2296FEL	N2SWSWSE	38.30671-99.59259	2-13	Alt. II completed, cement circulated to surface