

15-101-21566-0000

KCC OIL/GAS REGULATORY OFFICE

DATE 2/7/91

- New Situation
- Response to Request
- Follow-up

OPERATOR TomKat Ltd. # 5538

NAME P.O. Box 20403

LOCATION NE, SEC 1, T 20 S, R 29 ^W

& ADDRESS Wichita, KS 67208

LEASE McMillan Well # 1

PHONE NO. 316-684-6182 OTHER _____

COUNTY Lane

REASON FOR INVESTIGATION: Alternate II cementing

PROBLEM: _____

PERSON(S) CONTACTED: _____

FINDINGS: I arrived at the location at 1 p.m. The port collar was set at 2100'. Pumped 300
sx cement, good returns. Allied pumped 60/40 Pozmix 8% gel. Start-3 p.m., Finish-3:35

LEASE INSPECTION

COMPLAINT

FEB 10 1991
2-10-91

ACTION/RECOMMENDATIONS: _____ photos taken: _____

FIELD REPORT

Retain 1 copy Joint District Office
Send 1 copy Conservation Division

By Steve Middleton
2/7/91

LEASE INSPECTION

- YES NONE COMMENTS
- [] I.D. Sign []
 - [] Tank Battery []; Condition: good [] questionable [] overflowing []
 - [] Pits, tank battery []; Fluid depth ___ ft.; approx. size ___ ft x ___ ft
 - [] Pit, injection site []; Fluid depth ___ ft.; approx. size ___ ft x ___ ft
 - [] Gas venting []
 - [] Oil spill evidence []
 - [] Saltwater evidence []; Surface flow _____; seepage _____
 - [] Saltwater pipelines []; Seepage visible Yes/No; tested for leaks Yes/No
 - [] Flowing holes []
 - [] Abandoned wells []
 - [] TA wells []; Potential poll. prob. _____; currently producing _____
 - [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
 - [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
 - [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
 - [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
 - [] Monitoring records []
 - [] Gauge connections []: tubing _____; T/C annulus _____; C/SP annulus _____
 - [] Gauge connections []: tubing _____; T/C annulus _____; C/SP annulus _____
 - [] Gauge connections []: tubing _____; T/C annulus _____; C/SP annulus _____
 - [] Gauge connections []: tubing _____; T/C annulus _____; C/SP annulus _____

Lease cleanliness: very good _____ satisfactory _____ poor _____ very bad _____

Water samples taken _____

Reports prepared _____

+	+	+	+	+	+	+	+
+	+	+	+	+	+	+	+
+	+	+	+	+	+	+	+
+	+	+	+	+	+	+	+