KCC OIL/GAS REGULATORY OFFICES

Date: <u>10/01/13</u>	District: 01	Case #:					
	New Situation	Lease Inspection					
	Response to Request	Complaint					
	Follow-Up	Field Report					
	ш ,	.					
Operator License No: 3842	API Well Number: <u>15-101-22460-00-00</u>						
Op Name: Larson Engineering, Inc. dba Larson Operating Company	Spot: <u>NESESWSE</u>	Sec 20 Twp 18 S Rng 30 E / W					
Address 1: 562 W State RD 4	345 (334)	Feet from N/ S Line of Section					
Address 2:	, ,	Feet from FE/W Line of Section					
City: Olimtz	, ,	Long: 100.65457 Date: 10/1/13					
State: Kansas Zip Code: 67564 -8561		Well #: 1-20					
Operator Phone #: (620) 653-7368							
Reason for Investigation:							
Witness Alt.II							
Problem:							
None							
Persons Contacted:							
Findings:							
8-5/8"@276'W175sxs							
TD@4612'							
5.5@4611'W/125sxs							
Port Collar@2167'W/195sxs-smd-1/4#flo seal	I2%cc-15sxs to pit.						
	·	·					
·							
Action/Recommendations: Follow	Up Required Yes No	Date:					
	oproduite						
None Alt.II requirements have been met.		RECEIVED					
		KANSAS CORPORATION COMMISSION					
		OCT 1 0 2013					
		CONSERVATION DIVISION WICHITA, KS					
Verification Sources:		Photos Taken:					
RBDMS KGS TT	A Program	1010M.					
	ourthouse By:	what I / / Bre					
Other:		hael Maier					
Retain 1 Copy District Office RECEIVED							
Send I Copy to Conservation Division		Form:					

KCC DODGE CITY

BNY

Date: 10/01/13		-	District	: <u>01</u>	_	Lic	ense #: <u>3842</u>		
Op Name: 3842 Spot:			Spot: <u>N</u>	ESESW	SE	Sec <u>20</u> Twp <u>18</u>	S Rng <u>30</u>	E ✓ W	
County: Lane Lease !			ame: <u>Cleo</u> Weil #: <u>1-20</u>						
I.D. Sign Yes	No		n	Gas V	enting [Yes No		9	
Tank Battery Condition Condition: Good Questionable Overflowing			Pits Fluid Depth:ft; Approx. Size:ft. xft.						
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N					
Oil Spill Evidence				Flowing Holes					
Abandoned Well I	Potential Pollu	ition Problem	Yes No 🖸	Т	A Wells				
Lease Cleanliness Very Good Sa	tisfactory	Poor Very	் / Bad	М	onitoring	Records			
SWD/ER Injection Well Permit #: Pr Permit #: Pr Permit #: Pr	essure – Actua essure – Actua	al: psi; Aut al: psi; Aut al: psi; Aut	-	Tubin Tubin Tubin	g: g: g:	ions	; C/SP Annulu ; C/SP Annulu	ıs:	
API Number	Footages	Spot Location	GPS		Well #		Well Status		
15-101-22460-00-00	334FSL 1386FEL	NESESWSE	38.46872-100.6	65457_	1-20	Cement circulated	I to pit.		
							<u></u>	-	
	•							. . .	
				•	_				
	i		<u> </u>		_	<u> </u>			

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: _____