

KCC OIL/GAS REGULATORY OFFICES

Date: 09/17/13

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 30742

API Well Number: 15-135-25,660-00-00

Op Name: Palomino Petroleum, Inc.

Spot: SWNESE Sec 29 Twp 16 S Rng 24  E /  W

Address 1: 4924 SE 84th ST

2217 (2218) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

541 (524) Feet from  E /  W Line of Section

City: Newton

GPS: Lat: 38.62965 Long: 99.99435 Date: 9/17/13

State: Kansas Zip Code: 67114 -8827

Lease Name: BVL Well #: 1

Operator Phone #: (316) 799-1000

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8-5/8"@218"W/165sxs  
TD@4630'  
5-1/2"@4590"W/195sxs  
Port Collar@1826"W/150sxs-smd-1/4#floseal-2%cc-15sxs to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

KCC WICHITA  
SEP 25 2013  
RECEIVED

Verification Sources:

Photos Taken: 0

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
Other: _____		

By: \_\_\_\_\_  
Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

SEP 23 2013

KCC DODGE CITY

Form: \_\_\_\_\_

*AM*

Date: 09/17/13

District: 01

License #: 30742

Op Name: 30742

Spot: SWNESE Sec 29 Twp 16 S Rng 24  E  W

County: Ness

Lease Name: BVL Well #: 1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25,660-00-00	2218FSL 524FEL	SWNESE	38.62965-99.99435	1	Cement circulated to surface

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_