

KCC OIL/GAS REGULATORY OFFICES

Date: 09/10/13

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
 Op Name: American Warrior, Inc.  
 Address 1: 3118 Cummings Rd  
 Address 2: P.O. Box 399  
 City: Garden City  
 State: Ks. Zip Code: 67846 -  
 Operator Phone #: (785) 398-2270

API Well Number: 15-135-25650-00-00  
 Spot: NENWSWNW Sec 36 Twp 18 S Rng 21  E /  W  
 1550 (1558) Feet from  N /  S Line of Section  
 455 (461) Feet from  E /  W Line of Section  
 GPS: Lat: 38.44674 Long: 99.60264 Date: 9/10/13  
 Lease Name: Ryersee Well #: 2-36  
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

None

Findings:

8.625@  
 TD@4209'  
 5.5@4209'W125sxs  
 Port Collar@1322'W/135sxs-smd-1/4#floseal-2%cc-15sxs to pit.

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier  
 Michael Maier

Retain 1 Copy District Office  
 Send 1 Copy to Conservation Division

RECEIVED  
 SEP 19 2013

KCC DODGE CITY

KCC WICHITA

SEP 23 2013

RECEIVED

Form: \_\_\_\_\_

Date: 09/10/13

District: 01

License #: 4058

Op Name: 4058

Spot: NENWSWNW Sec 36 Twp 18 S Rng 21  E  W

County: Ness

Lease Name: Ryersee Well #: 2-36

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25650-00-00	1558FNL 461FWL	NENWSWNW	38.44674-99.60264	2-36	Cement circulated to pit

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_