KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/11/13</u>	District: <u>01</u>	Case	#:		
	New Situation	Lease Ins	pection		
	Response to Request	Complain	t		
	Follow-Up	√ Field Rep	ort		
Operator License No: 30742	API Well Number: <u>15-13</u>	35-25.646-00-00			
Op Name: Palomino Petroluem, Inc.	·				
Address 1: 4924 SE 84th St.			N/S Line of Section		
Address 2:	, ,		E/W Line of Section		
City: Newton	• •		Date: <u>9/11/13</u>		
State: Kansas Zip Code: 67114 -8827			Well #: _1		
Operator Phone #: (316) 799-1000					
Reason for Investigation:					
Witness Alt.li					
Problem:					
None					
Persons Contacted:		-			
Findings:					
8-5/8"@221'W/150sxs					
TD@4629'					
5.5@4623'W/175sxs					
Port Collar@1866'W/200sxs-smds-1/4#flose	al-2%cc-15sxs to pit.				
			i.		
Antica (Decrementation)					
	w Up Required Yes N	o 🖸 Date:			
None Alt.II requirements have been met.					
			;		
Verification Sources:			Photo Tuber (
		1000	Photos Taken:		
RBDMS	TA Program Countbourse By:	July UMa	·		
T-I Database District Files	Courthouse By:	111			
Other:RECEIVED		CC WICHITA			
Retain I Copy District Office Send I Copy to Conservation Division EP 1 9 2013	_				
''		SEP 23 2013	Form:		
KCC DODGE CITY		RECEIVED	Δ 1		

RECEIVED

Date: <u>09/11/13</u>		ı	Di	strict:	01		License	e #: <u>30742</u>	_
•			Sp	ot: <u>SE</u>	NESES	SE	Sec <u>11</u> Twp <u>17</u>	S Rng <u>26</u> E 🗸 W	V
County: Ness			Le	ase Nan	ne: <u>Nor</u>	ton-Que	nzer\	Well #: 1	_
I.D. Sign Yes N					Gas V	enting	Yes No	[2]	·]
Tank Battery Condit		e Overflowi	ng	•	Pit Fluid I		ft; Approx. Size: _	ft. xft.	
Pits, Injection Site Fluid Depth:	ft; Approx. Si	ze:ft.	x	ft.		ltwater Pij ks Visible:		ted for Leaks: Y N	.
Oil Spill Evidence					Fic	owing Hole	es		
Abandoned Well F	Potential Pollu	tion Problem	Yes N	lo 🖸		A Wells	Records		
Lease Cleanliness Very Good Sa	tisfactory	Poor Very	Bad	•		C			
SWD/ER Injection Well Permit #: Pro Permit #: Pro Permit #: Pro	Yes Actua essure – Actua essure – Actua	No ::psi; Aut ::psi; Aut	Ness horized: horized: horized:	psi psi	Tubin Tubin Tubin	g: g:	; T/C Annulus:; T/C Annulus:; T/C Annulus:	; C/SP Annulus:; C/SP Annulus:; C/SP Annulus:; C/SP Annulus:;	_
API Number	Footages	Spot Location	C	GPS		Well #		Well Status	_
15-135-25,646-00-00	694FSL 158FEL	SENESESE	38.58301	-100.1	5684	1	Cement circulated to	surface.	
			_						
									_

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: