

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. 103-37
LOCATION SW-SE-NW
SEC. 25 TWP. 34 RGE. 13W

Dry Hole X Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease McArthur
Operator Iron Dug Co Address 1306 Holloway Rdg Tulsa Okla
Field _____ County Bailey

Total Depth 4960 Feet.

Plugging Contractor R-S Pipe Pulling Co

Plugging Contractor's License No. 1

Address Ellenwood Kansas

(Describe Briefly the manner in which the well was plugged)

8 3/8" 250' C.W.C. 5 1/2" 4960' Cmt 75% Prof 4808'
hole filled with sand to 4900' run 5' cement
with chunk failer Mud 250' set Rock fudge
run 20' cement Mud to 35' set rock fudge 100'
Cement Pcp.

Jell Mud circulated through 5 1/2" at 1800'
Mud Pumped by Helpherton cementing Co

M L Reeves
District Conservation Agent

Date 10-6-56

RECEIVED
STATE CORPORATION COMMISSION
OCT 10 1956 10-10-56
CONSERVATION DIVISION
Wichita, Kansas

CR3

PLUGGING
FILE SEC. 25 T. 34 R. 13W
BOOK PAGE 103 LINE 37