

DISTRICT CONSERVATION AGENT'S REPORT

*R*  
*OB*

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. ✓

LOCATION SW-7N-7E

SEC. 19 TWP. 34 RGE. 8W

Dry Hole ✓ Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. 1 Lease Hanna Drwker 712  
Operator Morrison Drly Co Inc Address El Dorado Kans  
Field ✓ County Harper  
Total Depth 4749 Feet.

(Describe briefly the manner in which the well was plugged)

Grinded pits and circulated,  
Hole made solid at 250,  
15 sack cement spotted thru 8 joints  
of drill pipe.  
5 sack cement at top of surface  
pipe.

*Paul D. ...*  
District Conservation Agent  
Date 11-11-52

**RECEIVED**  
STATE CORPORATION COMMISSION  
NOV 12 1952  
PLUGGING  
FILE SEC 19 T 34 R 22  
BOOK PAGE 58 LINE 230  
CONSERVATION DIVISION  
Wichita, Kansas