KCC OIL/GAS REGULATORY OFFICES

Date: <u>08/20/13</u>	District: <u>01</u>
•	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Operator License No: <u>4767</u>	API Well Number: 15-057-20906-00-00
Op Name: Ritchie Exploration, Inc.	Spot: SE SW SE Sec 14 Twp 26 S Rng 23 E / W
Address 1: 8100 E 22ND ST N# 700	335 (336) Feet from N/ S Line of Section
Address 2: BOX 783188	1680 (1684) Feet from Feet from E/W Line of Section
City: Wichita	GPS: Lat: <u>37.77911</u> Long: <u>99.80242</u> Date: <u>8/20/13</u>
State: Kansas Zip Code: 67278 -3188	Lease Name: Galen Durler Well #: 1
Operator Phone #: (316) 691-9500	County: Ford
Reason for Investigation:	
Witness ALT. II	
Problem:	
None	
Persons Contacted:	
N/A	
Findings:	
8-5/8" @ 367'W/250sxs cmtTD@51204-1	/2"@5140'W/200sxs cmtPort Collar@1435-cemented with
250 sxs-smd-1/4#floseal-250# Hulls	
2%cc-20sxs cmt to pit	
Cement company: Consolidated	RECEIVED KANSAS CORPORATION COMMISSION
	SEP 0 4 2013
	CONSERVATION DIVISION WICHITA, KS
Action/Recommendations: Follow	v Up Required Yes No Date:
Alternate II cementing requirements have be	en met
Verification Sources:	Photos Taken: <u>0</u>
RBDMS KGS	TA Program
T-I Database	Courthouse By: Nathan Willis
Other:	
Retain 1 Copy District Office CEIVED Send 1 Copy to Conservation Division	
AUG 2 9 2013	Form:
KCC DODGE CITY	a a

A M

Date: <u>08/20/13</u>		-	District:	<u>U1</u>		License #: 4/6/		
Ор Name: <u>4767</u>			Spot: <u>S</u> E	SE SW SE Sec 14 Twp 26 S Rng 23 E W				
County: <u>Ford</u>			Lease Na	se Name: Galen Durler Well #: 1				
1.D. Sign Yes	No ·		.,	Gas Venting	Yes No		<u> </u>	
Tank Battery Cond		ole Overflow	ving	Pits Fluid Depth:	ft; Approx	s. Size:ft. x	fi.	
Dia Inicaio Cia	· · · · · · · · · · · · · · · · · · ·			Saltwater P	:!:a			
Pits, Injection Site Fluid Depth:	_ft; Approx. S	ize:ff	t. xft.	\vdash	e: Y N	Tested for Leaks:	Y N	
Oil Spill Evidence				Flowing Ho	les			
Abandoned Well	Potential Polli	ution Problem	Yes No · · ·	TA Wells	Danada			
L sass Classificans				Monitoring	Records			
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad					
SWD/ER Injection Well			Ford 🖸	Cauge Connect	ions Yes	No.		
Permit #: Pi		l.				:; C/SP Annulu		
Permit #: Pr						:; C/SP Annulu		
Permit #: Pi						:; C/SP Annulu		
Permit #:P			thorized: psi			:; C/SP Annulu		
		1 3, 131	<u></u> .			<u> </u>		
API Number	Footages	Spot Location	GPS	Well #		Well Status		
			_					
						·		
		<u> </u>	-					
						 		
	,							
				_				
						·		

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: