KCC OIL/GAS REGULATORY OFFICES

Date: 11/15/13	District: 01 Case #:
	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Operator License No: 30742	API Well Number: <u>15-135-25,682-00-00</u>
Op Name: Palomino Petroleum, Inc.	Spot: SENENWNE Sec 23 Twp 19 S Rng 24 E / W
Address 1: 4924 SE 84th ST	371 (404) Feet from N/ S Line of Section
Address 2:	1612 (1607) Feet from Feet from E / W Line of Section
City: Newton	GPS: Lat: 38.39139 Long: 99.94006 Date: 11/15/13
State: Kansas Zip Code: 67114 -8827	Lease Name: Benson Family Trust Well #: 1
Operator Phone #: <u>(316) 799-1000</u>	County: Ness
Reason for Investigation:	
Witness Alt.1I	
Problem:	
None	
Persons Contacted:	
Findings:	
8-5/8"@217'W/165sxs	
TD@4435'	
5-1/2"@4430'W/195sxs Port Collar@1517'W/130sxs-smd-1/4#floseal	l-2%cc-15eye to nit
	1-2 /800-103A3 to pit
Action/Recommendations: Follow	v Up Required Yes No 🖸 Date:
None, Alt.II requirements have been met.	KCC WICHITA
	NOV 25 2013
	RECEIVED
Verification Sources:	Photos Taken:
RBDMS KGS	TA Program M D D Mb
	Courthouse By: # White for the second
Other: RECEIVED	Michael Maier
Retain I Copy District Office	
Send I Copy to Conservation Division 2 0 2013	Form:
KCC DODGE CITY	

Date: 11/15/13		_		:: <u>U1</u>			ense #: <u>30742</u>		
Op Name: 30742 Spot: 5					SENENWNE Sec 23 Twp 19 S Rng 24 E V W				
County: Ness Lease					Name: Benson Family Trust Well #: 1				
I.D. Sign Yes	No		9	Gas '	Venting [Yes No		[5]	
Tank Battery Condition Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.					
Pits, Injection Site				Saltwater Pipelines					
Fluid Depth:	_ft; Approx. S	Size:fi	t. xft.				Tested for Leaks:	Y N	
Oil Spill Evidence				Flowing Holes					
Abandoned Well	Potential Poll	ution Problem [Yes No 🖸	7	TA Wells				
					Monitoring Records				
Lease Cleanliness			<u> </u>	Ш.					
	atisfactory	Poor Ver	y Bad						
SWD/ER Injection Well			Ness 🖭	Gaus	e Connect	ions Yes No		[2]	
Permit #: P			-				; C/SP Annulus:		
Permit #: P							; C/SP Annulus:		
Permit #: P	ressure – Actu	al: psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus:	; C/SP Annulus:		
Permit #: P	ressure – Actu	al:psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus:	; C/SP Annulus:		
API Number	Footages	Spot Location	GPS		Well #		Well Status		
15-135-25,682-00-00	404FNL 1607FEL	SENENWNE	38.39139-99.94	4006	1	Cement circulated	l to surface		
PAL DA	-								
, ,	' <u>-</u>								
			_		ļ				
			1		1				
			1						
<u> </u>		9,1	* · · · · · · · · · · · · · · · · · · ·		<u> </u>				
	j								

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: