## KCC OIL/GAS REGULATORY OFFICES

Date: 12/03/13	District: 01	Case #:				
	New Situation	Lease Inspection				
	Response to Request	Complaint				
	Follow-Up	Field Report				
Operator License No: 4058	API Well Number: <u>15-135-25702-00-00</u>					
Op Name: American Warrior, Inc	Spot: W2 NE SW SE	_Sec <u>12  Twp 19  S Rng 25  E / W</u> W				
Address 1: 3118 CUMMINGS Rd	990 (956)	Feet from N/S Line of Section				
Address 2: PO BOX 399		Feet from E/W Line of Section				
City: GARDEN CITY	GPS: Lat: <u>38.39471</u>	Long: 100.05128 Date: 12/3/13				
State: <u>KANSAS</u> Zip Code: <u>67846</u> –	Lease Name: <u>Jenetta</u>	Well #: _3-14				
Operator Phone #: <u>(620) 275-2963</u>	County: NESS.					
Reason for Investigation:						
Witness ALT. II						
Problem:						
N/A						
Persons Contacted:						
Jason With Swift. No American Warrior re	presentative at location					
Findings:						
8-5/8" @229'W/150sxsTD@45255-1/2'	'@4502'W/125sxsPort C	ollar@1612-cemented with 120				
sxs-smd-1/4#floseal						
2%cc-20sxs to pit						
·						
	ollow Up RequiredYes ✓ No	KCC WICHITA				
Alternate II cementing requirements have	been met					
		DEC 0 9 2013				
		RECEIVED				
		110011705				
N. T. d. G.		Dhatas TL O				
Verification Sources:		Photos Taken: 0				
RBDMS KGS	TA Program By: Natl	han Willis				
T-I Database ✓ District Files	Courthouse By. Nati					
Other:						
Retain 1 Copy District OfficRECEIVED Send 1 Copy to Conservation Division						
Solid , Sopy to Consolitation Division		Form:				

DEC - 4 2013 KCC DODGE CITY

Date: <u>12/03/13</u>		_	District	: <u>01</u>	Lice	nse #: <u>4058</u>	
Op Name: 4058			Spot: <u>W</u>	Spot: W2 NE SW SE Sec 12 Twp 19 S Rng 25 E			
County: NESS Lease			Lease Na	fame: <u>Jenetta</u> Well #: <u>3-14</u>			
I.D. Sign Yes	] No	-	. 5	Gas Venting	Yes No	9	
Tank Battery Cond		ole Overflow	ring in	Pits Fluid Depth:	ft; Approx. Size	e:ft. xft.	
Pits, Injection Site	<u> </u>			Saltwater Pi	inelines		
Fluid Depth:	_ft; Approx. S	Size:ff	t. xft.	Leaks Visible		ested for Leaks: Y N	
Oil Spill Evidence				Flowing Hol	les		
Abandoned Well	Potential Pollu	ution Problem [	Yes No	TA Wells			
Lease Cleanliness Very Good S	Satisfactory	Poor Ver	y Bad	Monitoring	Records		
SWD/ER Injection Wel			NESS 🖸	Gauge Connect	ions Yes No	<u></u>	
Permit #: P		•		_		; C/SP Annulus:	
Permit #: P	ressure – Actua	al: <u>,                                    </u>	thorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:	
Permit #: P	ressure – Actua	al: psi; Au	thorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:	
Permit #: P	ressure – Actua	al:psi; Au	thorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:	
API Number	Footages	Spot Location	GPS	Well#		Well Status	
-4 t E E E E	V 5 8 . St						
* 9 - 4	1 of 1						
<u> </u>	m ž						
<u></u>							

Retain I Copy District Office Send I Copy to Conservation Division

Form: