## KCC OIL/GAS REGULATORY OFFICES

Date: <u>12/11/13</u>	District: <u>01</u>		Case	#:			
	New Situation		Lease Ins	pection			
	Response to Reque	st	Complain	t			
	Follow-Up	✓	Field Rep	ort			
Operator License No: 31086	API Well Number: <u>15-135-25699-00-00</u>						
Op Name: Richlan Drilling, a General Partnership	Spot: <u>NW NW SE N</u>	ESec_22	Twp <u>19</u>	_S Rng <u>22</u> E / \sqrt{W}			
Address 1: 598 2ND AVE	1640 (1679)		Feet from	N/ S Line of Section			
Address 2:	1170 (1162)		Feet from	E / W Line of Section			
City: Beaver	GPS: Lat: 38.38810	Long: <u>99.7</u>	73698	Date: <u>12/11/13</u>			
State: KS Zip Code: 675259226	Lease Name: Rahm	·		Well #: 3			
Operator Phone #: (620) 587-3605	County: Ness						
Reason for Investigation:							
Witness Alt 2 cementing							
Problem:							
N/A							
Persons Contacted:							
Jason With Swift and Rick Schreiber with Ric	hlan.						
Findings:			<del></del>	<u> </u>			
	4476"M/150ava Dar	t Coller@14	E2 00m0	entod with all 175 ava			
8-5/8" @257'W/160sxsTD@44835-1/2"@- to surface	4476 W/15USXSPOI	Collar@14:	os-ceme	inted with all 175 SXS			
sxs-smd-1/4#floseal 2%cc-20sxs to pit							
one one in innecedia 27000 20000 to pic							
Action/Recommendations: Follow	Up Required Yes	No 🖸	Date:				
Successful Alt 2				KCC WICHITA			
				DEC 1 8 2013			
				RECEIVED			
Verification Sources:	· · · · · · · · · · · · · · · · · · ·			Photos Taken:			
RBDMS KGS	ſA Program						
	Courthouse By: 1	Nathan Willis					
Other							
RECEIVED \							
Send I Copy to Conservation Division DEC 1 3 2013				Form:			

KCC DODGE CITY

AN

Date: <u>12/11/13</u>		_	District	: <u>01</u>		License #: <u>31086</u>		
Op Name: 31086			Spot: N	<u>W NW SE N</u>	E Sec <u>22</u> Tv	vp <u>19</u> S Rng <u>22</u>	E 🕢 W	
County: Ness			Lease N	ame: Rahm Well #: 3				
I.D. Sign Yes	No		<b>5</b>	Gas Venting	g Yes No		يق	
Tank Battery Condition  Condition: Good Questionable Overflowing				Pits Fluid Depth	:ft; Appre	ox. Size:ft.	xft.	
D'4. I. ' 4' 6'4								
Pits, Injection Sit		iize:fi	t, xft.	<b></b>	r Pipelines sible: Y N	Tested for Leaks	S: Y N	
Oil Spill Evidence	e			Flowing	Holes			
Abandoned Well	Potential Pollo	ution Problem [	Yes No □	TA We	ls .			
				Monitor	ing Records			
Lease Cleanliness Very Good	Satisfactory	Poor Ver	y Bad					
SWD/ER Injection W	ell 🔲 Yes 🔲	No	Ness 🖸	Gauge Con	nections Yes	] No	1	
Permit #:	Pressure - Actua	al: psi; Au	thorized: psi	Tubing:	; T/C Annulı	us:; C/SP Ar	nulus:	
Permit #:	Pressure - Actua	al:psi; Au	thorized: psi			us:; C/SP Ar		
Permit #:						us:; C/SP A1		
Permit #:	Pressure - Actua	al: psi; Au	thorized: psi	Tubing:	; T/C Annulı	us:; C/SP Aı	ınulus:	
API Number	Footages	Spot Location	GPS	Wel	1#	Well Status		
. ,								
,								

Form: \_\_\_