

# KCC OIL/GAS REGULATORY OFFICES

Date: 12/12/13

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-25673-00-00

Op Name: American Warrior, Inc.

Spot: SWSESENW Sec 17 Twp 18 S Rng 21  E /  W

Address 1: 3118 Cummings Rd

2560 (2544) Feet from  N /  S Line of Section

Address 2: P.O. Box 399

2210 (2237) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.48756 Long: 99.67086 Date: 12/12/13

State: Ks. Zip Code: 67846 -

Lease Name: EHT Well #: 1-17

Operator Phone #: (785) 398-2270

County: Ness

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None

**Persons Contacted:**

*swift services personnel.*

**Findings:**

8.625@223W/150sxs  
TD@4313'  
5.5@4312"W145sxs  
Port Collar@1439"W/140sxs-smd-1/4#floseal-2%cc-15sxs to pit.

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

**Verification Sources:**

Photos Taken: 0

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

By: \_\_\_\_\_

Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**RECEIVED**

DEC 19 2013

KCC DODGE CITY

KCC WICHITA

DEC 31 2013

RECEIVED

Form: \_\_\_\_\_

*AMT*

Date: 12/12/13

District: 01

License #: 4058

Op Name: 4058

Spot: SWSEENW Sec 17 Twp 18 S Rng 21  E  W

County: Ness

Lease Name: EHT Well #: 1-17

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness

Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25673-00-00	2544FNL 2237FWL	SWSEENW	38.48756-99.67086	1-17	Cement circulated to pit

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

KOC MARCH 31 2013

Form: \_\_\_\_\_