

KCC OIL/GAS REGULATORY OFFICES

Date: 01/07/14

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 33927

API Well Number: 15-135-25.697-00-00

Op Name: Mustang Energy Corporation

Spot: W/2SWSWSE Sec 1 Twp 20 S Rng 22  E /  W

Address 1: P.O. Box 1121

330 (314) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2540 (2542) Feet from  E /  W Line of Section

City: Hays

GPS: Lat: 38.33563 Long: 99.70437 Date: 1/7/14

State: Kansas Zip Code: 67601 -

Lease Name: Dechant Unit Well #: 1

Operator Phone #: (785) 623-0533

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

\_\_\_\_\_

Findings:

8.625@218'W/150sxs  
TD@4389'  
4.5"@4388'W/130sxs  
Port Collar@1545'W/200sxs-smd-2%cc-1/4#flo seal-20sxs to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None Alt.II requirements have been met.

**KCC WICHITA**  
**JAN 16 2014**  
**RECEIVED**

Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation District  
**JAN 13 2014**  
**KCC DODGE CITY**

Form: \_\_\_\_\_

*Handwritten mark*

Date: 01/07/14

District: 01

License #: 33927

Op Name: 33927

Spot: W/2SWSWSE Sec 1 Twp 20 S Rng 22  E  W

County: Ness

Lease Name: Dechant Unit Well #: 1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25697-00-00	314FSL 2542FEL	W/2SWSWSE	38.33563-99.70437	1	Cement circulated to surface.

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_