

LSINS

KCC OIL/GAS REGULATORY OFFICES

Date: 06/18/12

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-24090-00-00

Op Name: American Warrior

Spot: SE Sec 35 Twp 18 S Rng 21 E / W

Address 1: P.O. Box 399

Feet from N / S Line of Section

Address 2: _____

Feet from E / W Line of Section

City: Garden City

GPS: Lat: _____ Long: _____ Date: _____

State: Kansas Zip Code: 67846 -0399

Lease Name: Ryervee Well #: 2-35--3-35--1

Operator Phone #: _____

County: Ness

Reason for Investigation:

Request for lease inspection

Problem:

Check on wells in SE quarter

Persons Contacted:

Scott Corsair, and Amy Banks

Findings:

Found two well producing and one well not producing, has swedge on casing, well info on back page. Scott Corsair said they would file plugging app. and get well plugged.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Send report to Amy Banks

Verification Sources:

Photos Taken: _____

- RBDMS
- T-I Database
- Other: _____
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Date: 06/18/12

District: 01

License #: 4058

Op Name: 4058

Spot: SE Sec 35 Twp 18 S Rng 21 E W

County: Ness

Lease Name: Ryersee Well #: 2-35--3-35--1

I.D. Sign Yes No

15-135-24-090-00-00

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24-090-00-00	2329FSL 353FEL	NE-SE-SE	38.44294-99.60544	2-35	Pumping with oil scars around well head
15-135-24097-00-00	116FSL 2260FEL	SW-SW-SE	38.43687-99.61202	3-35	Pumping with oil scars around well head
15-135-952-00-00	2009FSL 1940FEL	NW-SE	38.44207-99.61097	1	Swedge on casing, operator will get plugged

Retain 1 Copy District Office
Send 1 Copy to Conservation Division