KCC OIL/GAS REGULATORY OFFICES

Date: <u>01/28/14</u>	District: <u>01</u>
	New Situation Lease Inspection
· · · · · · · · · · · · · · · · · · ·	Response to Request Complaint
	Follow-Up Field Report
O	ADI W. II N 45 404 22405 00 00
Operator License No: 4767	API Well Number: <u>15-101-22485-00-00</u> Spot: <u>SESESW</u> Sec <u>13</u> Twp <u>18</u> S Rng <u>28</u> E / W
Op Name: Ritchie Exploration, Inc.	
Address 1: 8100E 22nd St N #700 Address 2: P.O. Box 73188	335 (353) Feet from N/\sqrt{S} Line of Section 2470 (2498) Feet from E/\sqrt{W} Line of Section
City: Wichita	GPS: Lat: 38.48201 Long: 100.36679 Date: 1/28/14
State: <u>Kansas</u> Zip Code: <u>62278</u> -3188	Lease Name: Hammeke Unit Well #: 1
Operator Phone #: (316) 691-9500	County: Lane
Reason for Investigation:	
Witness Alt.II	
Problem:	,
None	
110110	
Persons Contacted:	
Findings:	
8-5/8"@238W/170sxs	
TD@4717'	
5-1/2"@4709'W/200sxs Port Collar@2070'W/250sxs-60/40-6%gel-1/4	4#flo seal-450#hulls-15eys to nit
Of Collar@2070 W/2003x3-00/40-070gcl-1/4	THIO Scal-430#Halls-133X3 to pit.
: : : : : : : : : : : : : : : : : : : :	
Action/Recommendations: Follow	v Up Required Yes No Date:
None Alt.II requirements have been met.	
There's will require many been men	RECEIVED
·	
	FEB 1 2 2014
	KCC DODGE CITY
Verification Sources:	1)
	Photos Taken:
	TA Program Courthouse By: Mules Hou
Other:	Michael Mater
Retain 1 Copy District Office RECEIVED (KCC WICHITA
Send 1 Copy to Conservation Division	
FEB 1 2 2014 \\	FEB 1 8 2014
KCC DODGE CITY	RECEIVED

awy

Date: 01/28/14		_	District	: 01	_	License #: 4767			
Op Name: <u>4767</u>	. <u> </u>	•	Spot: <u>S</u>	ESESW		Sec <u>13</u> Twp <u>18</u>	S Rng <u>28</u>	□E 🗸 W	
County: Lane		·=	Lease Na	ame: <u>Han</u>	nmeke	Unit	Well #: <u>1</u>		
I.D. Sign Yes	No			Gas Ve	enting [Yes No			
Tank Battery Cond		ble Overflov	wing	Pits Fluid, I		ft; Approx. Size	:ft. x _	ft.	
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:1	ft. xft.	\vdash	twater P	- <u></u>	ested for Leaks:[Y N	
Oil Spill Evidence				Flo	wing Ho	les			
Abandoned Well	Potential Poll	ution Problem [Yes No 🔄	TA	Wells				
Lease Cleanliness Very Good S	atisfactory	Poor Ver	ry Bad	Мо	nitoring	Records			
SWD/ER Injection Well Permit #: P Permit #: P Permit #: P	ressure – Actu ressure – Actu	al: psi; Au al: psi; Au	Lane state s	Tubing Tubing	g:	ions	; C/SP Annı	ılus:	
Permit #: P			thorized: psi			; T/C Annulus:			
API Number	Footages	Spot Location	GPS		Well #		Well Status		
15-101-22485-00-00	353FSL 2498FWL	SESESW	38.48201-100.3	36679 1		Alt.II completed, ce	ment circulate	d to pit	
				-	<u>-</u> .				
		,		7					
	**************************************	Acar and	Section 1					· ·	
Retain 1 Copy District Office Send 1 Copy to Conservation	e	acina de mai							
Sena i Copy to Conservation	ייייייייייייייייייייייייייייייייייייי	00 11 113					Form:		

CAME (-1)