

KCC OIL/GAS REGULATORY OFFICES

Date: 3-6-14

District: 1

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 7311  
 Op Name: Shakespeare Oil Co Inc  
 Address 1: 202 W. Main St.  
 Address 2: \_\_\_\_\_  
 City: Salem  
 State: IL Zip Code: 62861-  
 Operator Phone #: 618 548 1585

API Well Number: 15-171-21026-0000  
 Spot: NWSESW Sec 36 Twp 16 S Rng 34  E /  W  
915 Feet from  N /  S Line of Section  
1880 Feet from  E /  W Line of Section  
 GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: \_\_\_\_\_  
 Lease Name: Janzen Well #: 3-36  
 County: Scott

Reason for Investigation:

Alt II Cementing

Problem:

\_\_\_\_\_

Persons Contacted:

\_\_\_\_\_

Findings:

8 7/8" @ 264'; 5 1/2" @ 4873' w/ 135sx. TD - 4880. Port Collor @ 2390'.  
Allied Cementing pumped 450sx 65/35 per 8% gel thru port collar.  
Circulated 20sx to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alternate II Complete

**KCC WICHITA**  
**MAR 14 2014**  
**RECEIVED**

Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Ken Schlik

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**RECEIVED**  
**MAR 12 2014**  
**KCC DODGE CITY**

Form: \_\_\_\_\_

*[Handwritten mark]*

Date: \_\_\_\_\_

District: \_\_\_\_\_

License #: \_\_\_\_\_

Op Name: \_\_\_\_\_

Spot: \_\_\_\_\_ Sec \_\_\_\_\_ Twp \_\_\_\_\_ S Rng \_\_\_\_\_  E  W

County: \_\_\_\_\_

Lease Name: \_\_\_\_\_ Well #: \_\_\_\_\_

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No

Gauge Connections  Yes  No

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

| API Number | Footages | Spot Location | GPS | Well # | Well Status |
|------------|----------|---------------|-----|--------|-------------|
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |