## KCC OIL/GAS REGULATORY OFFICES

Date: <u>04/04/14</u>	District: <u>01</u> New Situation			Case	Case #:			
				Lease Inspection				
	Respor	ise to Requ	iest.	Complai	int			
	Follow	-Up		Field Re	port			
				<u> </u>				
Operator License No: 4058			<u>5-135-257</u> 4		•			
Op Name: American Warrior, Inc.	Spot: <u>W/2</u> S	<u>SESWNE</u>	Sec	12 Twp <u>20</u>		بت ب		
Address 1: 3118 Cummings Rd						S Line of Section		
Address 2: P.O. Box 399	_1700	•		/		W Line of Section		
City: Garden City	GPS: Lat: _		Long:	· · · · · · · · · · · · · · · · · · ·	Date:	4/4/14		
State: Ks. Zip Code: 67846 -	Lease Name:	Ben Hir	nergardt		_ Well #: _4	4		
Operator Phone #: (785) 398-2270	County: Ne	ess .						
Reason for Investigation:								
Witness Alt.II				·				
Problem:				٠		•		
None			1					
					•			
Persons Contacted:								
	•		•					
Findings:		•	•			· · · · · · · · · · · · · · · · · · ·		
8.625@212W/150sxs TD@4387'		· · .				•		
5.5@4387'W175sxs								
Port Collar@1429'W/120sxs-smd-1/4#floseal	l-2%cc-15s>	ks to pit.						
					÷			
			-					
			ŧ		•			
		•				•		
Action/Recommendations: Follow	v Up Required	Yes	No 🖺	Date: _		<i>-</i>		
None, Alt.II requirements have been met.				•	4			
				KCC	WICHI	TA		
				APR	1 0 2014	}		
	,			RI	ECEIVEI	D		
Verification Sources:	1				Photos '			
	EA Decore		h1 1	1000	1/1			
│ <del>                                    </del>	ΓA Program	Ву:_	Mulio	J / ///	(au)			
T-I Database	Courthouse		Michael M	aier				
					····	_		
Retain I Copy District Office Send I Copy to Conservation Division  APR - 8 2014								
			•		Form:			

nom

O. N. 4059		_		OCECA/NE	• •	C D . 24			
Op Name: 4058				Spot: W/2SESWNE Sec 12 Twp 20 S Rng 21 E  Lease Name: Ben Hinnergardt Well #: 4					
County: Ness			Lease Na	me: <u>Ben Hinner</u>	garui				
I.D. Sign Yes	No			Gas Venting	Yes No	· · · · · · · · · · · · · · · · · · ·			
Tank Battery Cond	lition			Pits					
Condition: Good		ble Overflow	ing		ft; Approx. Si	ze:ft. xft.			
Pits, Injection Site	,			Saltwater Pi	ipelines				
Fluid Depth:	_ft; Approx. S	Size:ft	. xft.	Leaks Visible	∷∏ Y∏ N	Tested for Leaks: Y N			
Oil Spill Evidence				Flowing Hol	les				
Abandoned Well	Potential Poll	ution Problem	Yes No 🖾	TA Wells					
1	•			Manitarian	Danauda				
Lease Cleanliness				Monitoring	Records	·			
	atisfactory	Poor Very	Bad			·			
SWD/ER Injection Well	Yes _	No	Ness 🔄	Gauge Connect	ions Yes No	13			
Permit #:P			horized: psi,			; C/SP Annulus:			
Permit #: P Permit #: P			horized: psi horized: psi			; C/SP Annulus:; C/SP Annulus:			
Permit #: P			horized: psi			; C/SP Annulus:			
		<del></del>		<del></del>					
API Number	Footages	Spot Location	GPS	Well #		Well Status			
15-135-25744-00-00	2318FNL	W/2SESWNE	38.32856-99.59 <u>(</u>	058 4	Cement circulated	I to pit			
10 100 20144 00 00	10001 EE	WIZGLOWINE	00.02000 00.000						
A Sight		<i>2</i> 7€		*		<u> </u>			
748 f									
\$ 1800									
		*.							
		3 7							
	1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	4 · · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		* .				
			·						
						•			

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: