KCC OIL/GAS REGULATORY OFFICES

Date: <u>04/15/14</u>	District: <u>01</u>					
	New Situation / Lease Inspection					
• .	Response to Request Complaint					
9	Follow-Up Field Report					
Operator License No: 9408	API Well Number: 15-101-00069-00 (
Op Name: Trans Pacfic Oil Corporation	Spot: <u>SWNE</u> Sec <u>23</u> Twp <u>16</u> S Rng <u>27</u> □E / ₩					
Address 1: 100 S Main Ste 200	1980 (1806) Feet from VN/ S Line of Section					
Address 2:	1980 (1987) Feet from Feet from E / W Line of Section					
City: Wichita	GPS: Lat: 38.64896 Long: 100.27354 Date: 4/15/14					
State: Kansas Zip Code: 67202 -3735	Lease Name: Clarence A Well #: 1-23					
Operator Phone #: (316) 262-3596	County: Lane					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None						
Persons Contacted:						
· :						
·						
Findings:						
8-5/8"@139' TD@4438' 5-1/2"@4398'W/145sxs	al 20/ as 15ava to pit					
Port Collar@2062'W/200sxs-smd-1/4#flosea	al-2%cc-15sxs to pit					
	·					
·						
Action/Recommendations: Follo	ow Up Required Yes No 🔯 Date:					
None, Alt.II requirements have been met.	VCC MICHITA					
	KCC WICHITA					
	APR 2 8 2014					
	RECEIVED					
Verification Sources:	Photos Taken:					
RBDMS KGS T-I Database District Files Other: RECEIVED	TA Program Courthouse By: MCMel Majer					
Retain I Copy District Office Send I Copy to Conservation Air Ror 2 2 2014						
KCC DODGE CITY	Form:					
KOO DODGE OH I						

Date: <u>04/15/14</u>		- .	District:	01		Lice	ense #: <u>9408</u>	
Op Name: <u>9408</u>			Spot: <u>SWNE</u>		Sec <u>23</u> Twp <u>16</u>	wp <u>16 S Rng 27 E</u> V		
County: Lane L			Lease Nai	ne: <u>Clare</u>	nce A		Well #: 1-23	
I.D. Sign Yes	No		·	Gas Ven	ting [Yes No		
Tank Battery Cond	ition			Pits				
Condition: Good	Questional	ole Overflov	ving	Fluid De	pth:	ft; Approx. Siz	e:ft. x _	ft.
Pits, Injection Site				Saltw	vater Pi	pelines	<u> </u>	
Fluid Depth:	_ft; Approx. S	Size:f	t. xft.	Leaks	Visible	: Y N	Tested for Leaks:	YN
Oil Spill Evidence		·		Flow	ing Hol	es		
Abandoned Well	Potential Poll	ution Problem [Yes No 📆	TA	Wells			
					•		;	
				Monitoring Records				
Lease Cleanliness Very Good S	atisfactory	Poor Ver	ry Bad					
SWD/ER Injection Well Permit #:P	Yes [No	Lane 🔝	_		ons Yes No	•	ulus:
Permit #: P	ressure – Actu	al: psi; Au	thorized: psi	Tubing:		; T/C Annulus:	; C/SP Anni	ulus:
Permit #: psi; Authorized: psi				Tubing:; T/C Annulus:; C/SP Annulus:				
Permit #:P	ressure – Actu	al: psi; Au	thorized: psi	Tubing:		; T/C Annulus:	; C/SP Anno	ulus:
API Number	Footages	Spot Location	GPS	V	Vell #		Well Status	
15-101-00069-00-00	1806FNL 1987FEL	SWNE	38.64896-100,2	7354 1-	23	Cement circulated to surface		
ACHOIN OC	.,					,		
1963 8 8 20 W				. ,				
CHARACTER							,	
L		<u> </u>	<u> </u>			L		