TATE CORP		API NUMBER 15-033-20,230 -00-C
Wichita S	ORATION COMMISSION tate Office Bldg. Plugging Section	C NE NE , SEC. 21 , T 32 S, R 17 W/
130 S. Mai	rket, Room 2078	4620 feet from S section line
Wichita, KS 67202 TECHNICIAN'S PLUGGING REPORT		660 foot from E section line
	30157	Lease Name Belcher Well J A-1
	•	•
ame&	B R G Petroleum, Inc. 7134 S. Yale, #600	County Comanche 193.38
ddress		Well Total Depth 5950foe
	Tulsa, OK 74136	Gonductor Pipe: Size feet
		, Surface Casing: Size 8 5/8 feet 590
benconed.	Oli Well X Gas Well	Input Well SWD Well 04A
ther wel	1 as hereinafter indicated	
'tugging	Contractor Mike's Testing &	Salvage, Inc. License Number 31529
iddress:	P.O. Box 209, Chase, KS 67524	· · · · · · · · · · · · · · · · · · ·
Company t	o plug at: Hour: 10 a.m. Day	y: 11 Honth: 4 Year:19 95
	proposal received from Ric	· · · · · · · · · · · · · · · · · · ·
	Mikes Testing & Salvage,	
. 5 ¹	2" at 5205' w/175 sx cement, P	erfs at 5140-42, 4081-86'
		sx cement on top of sand through bailer,
	at 1110' with 50 sx cement,	
2-4 -1		
org brug	at 650' with 50 sx cement,	\
	at 40° with 20 sx cement.	
	at 40° with 20 sx cement.	
	at 40° with 20 sx cement.	Proposal Received by Steve Durrant (TECHNICIAN)
4th plug	at 40° with 20 sx cement. Plugging	Proposal Received by Steve Durrant
4th plug	at 40° with 20 sx cement. Plugging Operations attended by Agent?	Proposal Received by Steve Durrant (TECHNICIAN) 1: All X Part None
4th plug Plugging Operation	at 40° with 20 sx cement. Plugging Operations attended by Agent? ns Completed: Hour:12:30 p.m.0	Proposal Received by Steve Durrant (TECHNICIAN) State
4th plug Prugging Operation	at 40' with 20 sx cement. Plugging Operations attended by Agent? ns Completed: Hour: 12:30 p.m.D LUGGING REPORT 1st plug sanded	Proposal Received by Steve Durrant (TECHNICIAN) Steve Durrant (TECHNICIAN) None Day: 11 Month: 4 Year:19 95 d back to 4050' and dumped 5 sx cement on top of san
Prugging Operation ACTUAL P	Plugging Operations attended by Agent? ns Completed: Hour:12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through	Proposal Received by Steve Durrant (TECHNICIAN) State of the St
Prugging Operation ACTUAL P through b	Plugging Operations attended by Agent? ns Completed: Hour: 12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through	Proposal Received by Steve Durrant (TECHNICIAN) State of the St
Prugging Operation ACTUAL P through b	Plugging Operations attended by Agent? ns Completed: Hour:12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through	Proposal Received by Steve Durrant (TECHNICIAN) State Durrant (TECHNICIAN) State Durrant (TECHNICIAN) State Durrant (TECHNICIAN) State Durrant (TECHNICIAN) All X Part None Day: 11
Prugging Operation ACTUAL P through b 2nd plug 3rd plug	Plugging Operations attended by Agent? ns Completed: Hour: 12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through	Proposal Received by Steve Durrant (TECHNICIAN) Steve Durrant (TECHNICIAN) Steve Durrant (TECHNICIAN) Steve Durrant (TECHNICIAN) None Day: 11
Prugging Operation ACTUAL P through b 2nd plug 3rd plug	Operations attended by Agent? Is Completed: Hour:12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through at 1110 with 50 sx cement, at 650 with 50 sx cement,	Proposal Received by Steve Durrant (TECHNICIAN) State Part None Day: 11 Month: 4 Year:19 95 d back to 4050' and dumped 5 sx cement on top of san h casing with gel spacers in between the same of
Prugging Operation ACTUAL P through b 2nd plug 3rd plug 4th plug	Plugging Operations attended by Agent? ns Completed: Hour:12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through at 1110' with 50 sx cement, at 650' with 50 sx cement, at 40' with 20 sx cement.	Proposal Received by Steve Durrant (TECHNICIAN) Start None Day: 11 Month: 4 Year:19 95 d back to 4050' and dumped 5 sx cement on top of san h casing with gel spacers in between the same of the
Prugging Operation ACTUAL P through b 2nd plug 3rd plug 4th plug	Plugging Operations attended by Agent? Ins Completed: Hour: 12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through at 1110' with 50 sx cement, at 650' with 50 sx cement, at 40' with 20 sx cement. Used 60/40 Pozmix 6% gel by A	Proposal Received by Steve Durrant (TECHNICIAN) Start None Day: 11 Month: 4 Year:19 95 d back to 4050' and dumped 5 sx cement on top of san h casing with gel spacers in between the same to the
Prugging Operation ACTUAL P through b 2nd plug 3rd plug 4th plug	Plugging Operations attended by Agent? Ins Completed: Hour: 12:30 p.m. LUGGING REPORT 1st plug sanded pailer. Spotted cement through at 1110' with 50 sx cement, at 650' with 50 sx cement, at 40' with 20 sx cement. Used 60/40 Pozmix 6% gel by Agent?	Proposal Received by Steve Durrant (TECHNICIAN) I: All X
Prugging Operation ACTUAL P through be 2nd plug 3rd plug 4th plug Remarks:	Plugging Operations attended by Agent? Ins Completed: Hour: 12:30 p.m.D LUGGING REPORT 1st plug sanded pailer. Spotted cement through at 1110' with 50 sx cement, at 650' with 50 sx cement, at 40' with 20 sx cement. Used 60/40 Pozmix 6% gel by A	Proposal Received by Steve Durrant (TECHNICIAN) I: All X