

KCC OIL/GAS REGULATORY OFFICES

Date: 04/18/14

District: 1

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-145-21754-00-00

Op Name: American Warrior Inc.

Spot: W/2 NE NE SW Sec 18 Twp 20 S Rng 20  E /  W

Address 1: PO Box 399

2310 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2000 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: \_\_\_\_\_

State: KS Zip Code: 67846 -0399

Lease Name: HT Well #: 1-18

Operator Phone #: (620) 275-2963

County: Pawnee

Reason for Investigation:

Company requested a witness to a port collar cement job.

Problem:

Alternate II cement requirements have not been met.

Persons Contacted:

Kim Hagens w/ American *Warrior*

Findings:

8:50 AM

8.625" Surface pipe set @ 221' w/ 150 sx cement.

5.5" Production casing set @ 4376' w/ 175 sx cement on the primary job

HD Well service opened up the port collar @ 1409'. Swift Services pumped 150sx SMD Cement w1/4 # floseal through the port collar. Good Circulation throughout the job. Circulated 20 sx cement to the reserve pit.

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

The Alternate II cementing requirements have been met.

KCC WICHITA

MAY 06 2014

RECEIVED

Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: *Richard Lacey*  
Richard Lacey

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED

APR 29 2014

KCC DODGE CITY

Form: \_\_\_\_\_

*RAW*

Date: 04/18/14

District: 1

License #: 4058

Op Name: 4058

Spot: W/2 NE NE SW Sec 18 Twp 20 S Rng 20  E  W

County: Pawnee

Lease Name: HT Well #: 1-18

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Pawnee

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_