

KCC OIL/GAS REGULATORY OFFICES

Date: 04/25/14

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-083-21906-00-00

Op Name: American Warrior, Inc.

Spot: NESWSESE Sec 3 Twp 23 S Rng 24  E /  W

Address 1: 3118 Cummings Rd

.335 (353) Feet from  N /  S Line of Section

Address 2: P.O. Box 399

967 (974) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.07438 Long: 99.93909 Date: 4/25/14

State: Ks Zip Code: 67846 -

Lease Name: Fritzler Well #: 3

Operator Phone #: (785) 398-2270

County: Hodgeman

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8.625@221'W/150sxs  
TD@4640'  
5.5@4627'W125sxs  
Port Collar@1443'W/125sxs-smd-1/4#flo seal-2%cc-15sxs to pit.

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

KCC WICHITA  
MAY 06 2014  
RECEIVED

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier  
Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division  
**RECEIVED**  
APR 29 2014

Form: \_\_\_\_\_

KCC DODGE CITY

*Handwritten mark*

Date: 04/25/14

District: 01

License #: 4058

Op Name: 4058

Spot: NESWSESE Sec 3 Twp 23 S Rng 24  E  W

County: Hodgeman

Lease Name: Fritzler Well #: 3

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21906-00-00	353FSL 974FEL	NESWSESE	38.07438-99.93909	3	Cement circulated to pit